

## DAMAGE PHOTO DOCUMENTATION

Claim Number: WD-2025-92273

Claimant: Maria Schmidt

Date of Photos: 2024-03-25

Damage Type: Water Damage

Damaged Object: basement flooring

Location: 80331 Munich

### PHOTO EVIDENCE:

Photo 1: Overview of the damaged basement flooring showing water stain patterns and discoloration across the entire surface.

Photo 2: Close-up of the burst/leaking pipe connection point. Visible corrosion and water residue around the joint.

Photo 3: Detail shot of water damage to the basement flooring showing material swelling and deformation.

Photo 4: Wide angle view showing the extent of flooding and water marks on surrounding walls.

Photo 5: Moisture meter reading on the basement flooring surface showing elevated humidity levels.

### DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the basement flooring at the property of Maria Schmidt in Munich.

Leaking dishwasher connection caused slow water damage over several weeks. The basement flooring shows extensive water damage including swelling and discoloration. Professional repair is required.

The damage was first discovered on 2024-03-23.

These photographs were taken on 2024-03-25 to document the current condition for insurance claim processing.

Assessment: The basement flooring requires professional repair.

Documented by: Maria Schmidt