

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2024-17223

Claimant: Markus Leitner

Date of Photos: 2025-11-01

Damage Type: Glass Damage

Damaged Object: balcony glass door

Location: 55116 Mainz

PHOTO EVIDENCE:

Photo 1: Full view of the shattered balcony glass door. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the balcony glass door. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the balcony glass door. Safety concern documented.

Photo 4: The frame and mounting of the balcony glass door showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged balcony glass door for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the balcony glass door at the property of Markus Leitner in Mainz.

During a break-in attempt, the intruder smashed the balcony glass door. While nothing was stolen, the balcony glass door is completely destroyed. Police report has been filed (reference included).

The damage was first discovered on 2025-10-31.

These photographs were taken on 2025-11-01 to document the current condition for insurance claim processing.

Assessment: The balcony glass door requires complete replacement.

Documented by: Markus Leitner