

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2025-25119

Claimant: Petra Wolf

Date of Photos: 2025-02-05

Damage Type: Glass Damage

Damaged Object: living room window pane

Location: 65183 Wiesbaden

PHOTO EVIDENCE:

Photo 1: Full view of the shattered living room window pane. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the living room window pane. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the living room window pane. Safety concern documented.

Photo 4: The frame and mounting of the living room window pane showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged living room window pane for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the living room window pane at the property of Petra Wolf in Wiesbaden.

The living room window pane shattered unexpectedly due to thermal stress. Glass fragments were found across the room. Temporary boarding has been applied for security. Professional glazier assessment confirms the living room window pane needs full replacement.

The damage was first discovered on 2025-02-03.

These photographs were taken on 2025-02-05 to document the current condition for insurance claim processing.

Assessment: The living room window pane requires complete replacement.

Documented by: Petra Wolf