

## DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2025-45027

Claimant: Klaus Weber

Date of Photos: 2024-03-16

Damage Type: Glass Damage

Damaged Object: patio sliding door glass

Location: 20095 Hamburg

### PHOTO EVIDENCE:

Photo 1: Full view of the shattered patio sliding door glass. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the patio sliding door glass. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the patio sliding door glass. Safety concern documented.

Photo 4: The frame and mounting of the patio sliding door glass showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged patio sliding door glass for security.

### DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the patio sliding door glass at the property of Klaus Weber in Hamburg.

During a break-in attempt, the intruder smashed the patio sliding door glass. While nothing was stolen, the patio sliding door glass is completely destroyed. Police report has been filed (reference included).

The damage was first discovered on 2024-03-15.

These photographs were taken on 2024-03-16 to document the current condition for insurance claim processing.

Assessment: The patio sliding door glass requires complete replacement.

Documented by: Klaus Weber