

DAMAGE PHOTO DOCUMENTATION

Claim Number: GD-2025-49224

Claimant: Wolfgang Fischer

Date of Photos: 2024-07-07

Damage Type: Glass Damage

Damaged Object: balcony glass door

Location: 44135 Dortmund

PHOTO EVIDENCE:

Photo 1: Full view of the shattered balcony glass door. Spider-web crack pattern visible across the entire pane.

Photo 2: Close-up of the point of impact on the balcony glass door. Clear radial fracture lines emanating from center.

Photo 3: Glass fragments on the floor below the balcony glass door. Safety concern documented.

Photo 4: The frame and mounting of the balcony glass door showing condition for replacement assessment.

Photo 5: Temporary boarding/covering installed over the damaged balcony glass door for security.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the balcony glass door at the property of Wolfgang Fischer in Dortmund.

A stray ball from neighboring children struck the balcony glass door, causing it to crack and partially shatter. The balcony glass door is now a safety hazard and must be replaced immediately.

The damage was first discovered on 2024-07-07.

These photographs were taken on 2024-07-07 to document the current condition for insurance claim processing.

Assessment: The balcony glass door requires complete replacement.

Documented by: Wolfgang Fischer