

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2024-21255

Claimant: Claudia Zimmermann

Date of Photos: 2024-08-16

Damage Type: Storm Damage

Damaged Object: terrace canopy

Location: 76131 Karlsruhe

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the terrace canopy. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the terrace canopy.

Photo 3: Fallen tree branch / debris that caused the damage to the terrace canopy.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the terrace canopy showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the terrace canopy at the property of Claudia Zimmermann in Karlsruhe.

Tornado-like wind conditions caused the terrace canopy to collapse entirely. The structural integrity is compromised beyond repair. Emergency securing measures have been taken.

The damage was first discovered on 2024-08-15.

These photographs were taken on 2024-08-16 to document the current condition for insurance claim processing.

Assessment: The terrace canopy requires professional repair.

Documented by: Claudia Zimmermann