

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2024-30765

Claimant: Markus Leitner

Date of Photos: 2025-10-10

Damage Type: Storm Damage

Damaged Object: chimney cap

Location: 55116 Mainz

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the chimney cap. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the chimney cap.

Photo 3: Fallen tree branch / debris that caused the damage to the chimney cap.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the chimney cap showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the chimney cap at the property of Markus Leitner in Mainz.

A large tree branch fell during the storm and crashed into the chimney cap, causing significant structural damage. The chimney cap is no longer functional and requires complete replacement.

The damage was first discovered on 2025-10-07.

These photographs were taken on 2025-10-10 to document the current condition for insurance claim processing.

Assessment: The chimney cap requires complete replacement.

Documented by: Markus Leitner