

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2024-53791

Claimant: Monika Steiner

Date of Photos: 2025-11-03

Damage Type: Storm Damage

Damaged Object: garden shed

Location: 30159 Hanover

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the garden shed. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the garden shed.

Photo 3: Fallen tree branch / debris that caused the damage to the garden shed.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the garden shed showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the garden shed at the property of Monika Steiner in Hanover.

Hailstorm with golf-ball sized hail stones severely damaged the garden shed. Multiple impact marks and cracks are visible. A professional assessment confirms total replacement is needed.

The damage was first discovered on 2025-11-01.

These photographs were taken on 2025-11-03 to document the current condition for insurance claim processing.

Assessment: The garden shed requires complete replacement.

Documented by: Monika Steiner