

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2024-61738

Claimant: Maria Schmidt

Date of Photos: 2024-05-30

Damage Type: Storm Damage

Damaged Object: roof tiles

Location: 80331 Munich

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the roof tiles. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the roof tiles.

Photo 3: Fallen tree branch / debris that caused the damage to the roof tiles.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the roof tiles showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the roof tiles at the property of Maria Schmidt in Munich.

A large tree branch fell during the storm and crashed into the roof tiles, causing significant structural damage. The roof tiles is no longer functional and requires complete replacement.

The damage was first discovered on 2024-05-30.

These photographs were taken on 2024-05-30 to document the current condition for insurance claim processing.

Assessment: The roof tiles requires complete replacement.

Documented by: Maria Schmidt