

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2024-63436

Claimant: Monika Steiner

Date of Photos: 2025-05-10

Damage Type: Storm Damage

Damaged Object: solar panels

Location: 30159 Hanover

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the solar panels. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the solar panels.

Photo 3: Fallen tree branch / debris that caused the damage to the solar panels.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the solar panels showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the solar panels at the property of Monika Steiner in Hanover.

Tornado-like wind conditions caused the solar panels to collapse entirely. The structural integrity is compromised beyond repair. Emergency securing measures have been taken.

The damage was first discovered on 2025-05-08.

These photographs were taken on 2025-05-10 to document the current condition for insurance claim processing.

Assessment: The solar panels requires complete replacement.

Documented by: Monika Steiner