

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2024-97986

Claimant: Thomas Mueller

Date of Photos: 2024-09-25

Damage Type: Storm Damage

Damaged Object: solar panels

Location: 10115 Berlin

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the solar panels. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the solar panels.

Photo 3: Fallen tree branch / debris that caused the damage to the solar panels.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the solar panels showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the solar panels at the property of Thomas Mueller in Berlin.

Severe storm with wind speeds exceeding 100 km/h tore off several solar panels. Debris was scattered across the property. Temporary covering has been applied to prevent further water ingress.

The damage was first discovered on 2024-09-22.

These photographs were taken on 2024-09-25 to document the current condition for insurance claim processing.

Assessment: The solar panels requires complete replacement.

Documented by: Thomas Mueller