

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2025-27498

Claimant: Georg Braun

Date of Photos: 2025-08-01

Damage Type: Storm Damage

Damaged Object: terrace canopy

Location: 68159 Mannheim

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the terrace canopy. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the terrace canopy.

Photo 3: Fallen tree branch / debris that caused the damage to the terrace canopy.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the terrace canopy showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the terrace canopy at the property of Georg Braun in Mannheim.

Storm-force winds ripped the terrace canopy from its mounting. The terrace canopy landed in the neighbor's garden. No injuries reported but the property damage is substantial.

The damage was first discovered on 2025-07-30.

These photographs were taken on 2025-08-01 to document the current condition for insurance claim processing.

Assessment: The terrace canopy requires complete replacement.

Documented by: Georg Braun