

DAMAGE PHOTO DOCUMENTATION

Claim Number: SD-2025-78390

Claimant: Sabine Hoffmann

Date of Photos: 2025-01-27

Damage Type: Storm Damage

Damaged Object: chimney cap

Location: 70173 Stuttgart

PHOTO EVIDENCE:

Photo 1: Overview of storm damage to the chimney cap. Visible structural displacement and debris.

Photo 2: Close-up of the impact point where wind/debris struck the chimney cap.

Photo 3: Fallen tree branch / debris that caused the damage to the chimney cap.

Photo 4: Wide angle of the property showing overall storm damage context.

Photo 5: Detail of the chimney cap showing cracks, breaks, and structural compromise.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the chimney cap at the property of Sabine Hoffmann in Stuttgart.

Severe storm with wind speeds exceeding 100 km/h tore off several chimney cap. Debris was scattered across the property. Temporary covering has been applied to prevent further water ingress.

The damage was first discovered on 2025-01-27.

These photographs were taken on 2025-01-27 to document the current condition for insurance claim processing.

Assessment: The chimney cap requires complete replacement.

Documented by: Sabine Hoffmann