

DAMAGE PHOTO DOCUMENTATION

Claim Number: WD-2024-64844

Claimant: Christian Maier

Date of Photos: 2025-10-05

Damage Type: Water Damage

Damaged Object: laundry room floor

Location: 28195 Bremen

PHOTO EVIDENCE:

Photo 1: Overview of the damaged laundry room floor showing water stain patterns and discoloration across the entire surface.

Photo 2: Close-up of the burst/leaking pipe connection point. Visible corrosion and water residue around the joint.

Photo 3: Detail shot of water damage to the laundry room floor showing material swelling and deformation.

Photo 4: Wide angle view showing the extent of flooding and water marks on surrounding walls.

Photo 5: Moisture meter reading on the laundry room floor surface showing elevated humidity levels.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the laundry room floor at the property of Christian Maier in Bremen.

A corroded copper pipe in the wall burst during freezing temperatures. The resulting water leak damaged the laundry room floor significantly. Drying equipment has been installed.

The damage was first discovered on 2025-10-03.

These photographs were taken on 2025-10-05 to document the current condition for insurance claim processing.

Assessment: The laundry room floor requires complete replacement.

Documented by: Christian Maier