

DAMAGE PHOTO DOCUMENTATION

Claim Number: WD-2025-14301

Claimant: Thomas Mueller

Date of Photos: 2024-02-27

Damage Type: Water Damage

Damaged Object: dining room floor

Location: 10115 Berlin

PHOTO EVIDENCE:

Photo 1: Overview of the damaged dining room floor showing water stain patterns and discoloration across the entire surface.

Photo 2: Close-up of the burst/leaking pipe connection point. Visible corrosion and water residue around the joint.

Photo 3: Detail shot of water damage to the dining room floor showing material swelling and deformation.

Photo 4: Wide angle view showing the extent of flooding and water marks on surrounding walls.

Photo 5: Moisture meter reading on the dining room floor surface showing elevated humidity levels.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the dining room floor at the property of Thomas Mueller in Berlin.

Leaking dishwasher connection caused slow water damage over several weeks. The dining room floor shows extensive water damage including swelling and discoloration. Professional repair is required.

The damage was first discovered on 2024-02-27.

These photographs were taken on 2024-02-27 to document the current condition for insurance claim processing.

Assessment: The dining room floor requires professional repair.

Documented by: Thomas Mueller