

DAMAGE PHOTO DOCUMENTATION

Claim Number: WD-2025-39483

Claimant: Markus Leitner

Date of Photos: 2025-10-06

Damage Type: Water Damage

Damaged Object: basement flooring

Location: 55116 Mainz

PHOTO EVIDENCE:

Photo 1: Overview of the damaged basement flooring showing water stain patterns and discoloration across the entire surface.

Photo 2: Close-up of the burst/leaking pipe connection point. Visible corrosion and water residue around the joint.

Photo 3: Detail shot of water damage to the basement flooring showing material swelling and deformation.

Photo 4: Wide angle view showing the extent of flooding and water marks on surrounding walls.

Photo 5: Moisture meter reading on the basement flooring surface showing elevated humidity levels.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the basement flooring at the property of Markus Leitner in Mainz.

The washing machine supply hose ruptured overnight. Approximately 200 liters of water flooded the area, causing severe damage to the basement flooring. Emergency plumber was called to stop the leak.

The damage was first discovered on 2025-10-04.

These photographs were taken on 2025-10-06 to document the current condition for insurance claim processing.

Assessment: The basement flooring requires professional repair.

Documented by: Markus Leitner