

DAMAGE PHOTO DOCUMENTATION

Claim Number: WD-2025-45159

Claimant: Wolfgang Fischer

Date of Photos: 2024-02-21

Damage Type: Water Damage

Damaged Object: kitchen ceiling

Location: 44135 Dortmund

PHOTO EVIDENCE:

Photo 1: Overview of the damaged kitchen ceiling showing water stain patterns and discoloration across the entire surface.

Photo 2: Close-up of the burst/leaking pipe connection point. Visible corrosion and water residue around the joint.

Photo 3: Detail shot of water damage to the kitchen ceiling showing material swelling and deformation.

Photo 4: Wide angle view showing the extent of flooding and water marks on surrounding walls.

Photo 5: Moisture meter reading on the kitchen ceiling surface showing elevated humidity levels.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the kitchen ceiling at the property of Wolfgang Fischer in Dortmund.

Leaking dishwasher connection caused slow water damage over several weeks. The kitchen ceiling shows extensive water damage including swelling and discoloration. Professional repair is required.

The damage was first discovered on 2024-02-19.

These photographs were taken on 2024-02-21 to document the current condition for insurance claim processing.

Assessment: The kitchen ceiling requires complete replacement.

Documented by: Wolfgang Fischer