

DAMAGE PHOTO DOCUMENTATION

Claim Number: WD-2025-61838

Claimant: Wolfgang Fischer

Date of Photos: 2024-02-23

Damage Type: Water Damage

Damaged Object: laundry room floor

Location: 44135 Dortmund

PHOTO EVIDENCE:

Photo 1: Overview of the damaged laundry room floor showing water stain patterns and discoloration across the entire surface.

Photo 2: Close-up of the burst/leaking pipe connection point. Visible corrosion and water residue around the joint.

Photo 3: Detail shot of water damage to the laundry room floor showing material swelling and deformation.

Photo 4: Wide angle view showing the extent of flooding and water marks on surrounding walls.

Photo 5: Moisture meter reading on the laundry room floor surface showing elevated humidity levels.

DAMAGE ASSESSMENT NOTES:

The photographs above document the damage to the laundry room floor at the property of Wolfgang Fischer in Dortmund.

Toilet overflow due to a blocked drain caused water to spread across the floor. The laundry room floor absorbed water and now shows buckling and staining. Immediate replacement is needed.

The damage was first discovered on 2024-02-23.

These photographs were taken on 2024-02-23 to document the current condition for insurance claim processing.

Assessment: The laundry room floor requires professional repair.

Documented by: Wolfgang Fischer