

A photograph of a flat roof under construction. In the background, a blue Deere excavator is visible, partially obscured by a dense line of green trees. The roof surface is dark and appears to be covered in a layer of material, possibly gravel or a protective membrane, with some visible seams and textures. The lighting suggests it might be late afternoon or early morning, with soft shadows.

SPARKS CAR WASH, NEW CONSTRUCTION

THE PLANS SAID PVC.

WE SAID NO.



THE CALL

HERE'S WHY

The spec called for a felt backed PVC system.
We proposed a different roof and walked
the GC through why.



THE SYSTEM

60 MIL VERSICO EPDM

Fully adhered. About 4,780 square feet.

A photograph of a flat roof with two black drain covers. The roof surface is dark and appears to be made of asphalt or a similar material. In the background, there is a wall with a light-colored, textured surface and a dark vertical element. The word "DRAINAGE" is written in white capital letters across the middle of the image.

DRAINAGE

THREE DRAINS, THREE OVERFLOWS


Set with the GC and the plumber. We adjusted the tapered insulation so water reaches every one.



THE WARRANTY

**20 YEARS,
NO DOLLAR LIMIT**

Versico backs it. No cap on covered repairs.



FINISHED JULY 2026

THE BUILDING DECIDES THE SYSTEM

FREE ROOF EVALUATIONS



**SEND US A MESSAGE
TO BOOK YOURS**

SERVING NY AND CT