Intelligent Pipeline Defect Detection Report

Auto Detection Results

Original Image

Annotated Detection Results



Detected Defects Details:

Type: gas-pipelines, Confidence: 0.77, Location: (604.0, 434.5), Size: 1162.0x271.0

Type: gas-pipelines, Confidence: 0.73, Location: (589.0, 553.5), Size: 1190.0x85.0

Type: deformation, Confidence: 0.52, Location: (370.0, 329.0), Size: 708.0x78.0

Report Generated: 2026-04-14 21:42:16