

Hinds Laboratory

A08



[If you have comments, send additional information](#)

Address: 5734 South Ellis Avenue

Year Construction: 1969

Year Acquired: 1969

Architect: I.W. Colburn

Gross Square Feet: 131,592

Primary Use: Laboratory

Design Zone: Ellis Avenue

Last Major Renovation:

None; piecemeal office and lab renovations

Comments:

Getty Grant assessment 2004

REGULATORY STATUS

National Register: No

NR Historic District:

Hyde Park-Kenwood Historic District

Chicago HRS Color Code: None

1 - Site

Land Ownership Status: Owned

Location - Physical:

No Comment.

Location - Program Adjacency:

No Comment.

Location Comment:

Occupies prime location along Ellis Avenue and on Science Quad; in scale and materials it relates more directly to Kersten (north) and Crerar Library (west) than to Bookstore to the south. Service drives to Ingleside and the Bookstore adjacent to the building provide conflicts between pedestrian and vehicular circulation.

2 - Adaptability

Construction Type:

Reinforced concrete construction

Accessibility:

Entrance - Y; Bathrooms - P

Floor-to-Floor Height:

From drawings, typical floor to floor height is 12'-0"

Structural Capability:

Interior partitions generally masonry (brick or CMU) and non-load bearing; interior spaces are adaptable from structural standpoint. Structural drawings available; load calculations would require engineering analysis

Adaptability Exterior:

Deteriorated entrance ramp scheduled to be replaced.

Adaptability Interior:

See Adaptability Structure comment

Adaptability Physical Features:

No Comment.

Adaptability Structure:

Structural system is a cast concrete waffle slab that is 1'-3.5" deep and spaced at 3'-6" both ways which provides a flexible loading capacity. Structure is readily adaptable for laboratory/office functions with floor-to-floor heights suitable to accommodate laboratory functions.

3 - Building Envelope

Roof Type: Built-up (1990)

Exterior Facade:

Stone

Exterior Base: Limestone

Exterior Trim: Limestone and brick

4 - Heritage and Historic

Landmark Status:

No

National Register: No

NR Historic District:

Hyde Park-Kenwood Historic District

NR Comments:

is referenced in Appendix I in the category of post WWII buildings

CHRS Comments:

Not Listed as of July 2011

Heritage - Exterior:

Hinds Laboratory

A08

The severe limestone wall planes, projecting box bays, and decorative use of geometric brick accents are unique to this building. The articulation of tower elements accommodating ventilation and vertical circulation are a distinctive feature, as is the use of corbelled brick and box bay windows. A later ramp addition to the front entrance exhibits significant deterioration and is scheduled to be replaced.

Heritage - Interior:

The interior finishes are substantially original. Some offices and laboratory spaces have been renovated or reconfigured. The main lobby and public corridors feature concrete waffle-slab ceilings, limestone and brick wall surfaces, and brick flooring which are typical design features of its period of construction. First floor classrooms feature distinctive brick detailing on wall surfaces.

Significant Spaces Identified:

No Comment.

Heritage Culture Elements:

Ceramic mural by noted artist Ruth Duckworth located in entryway

Architectural Awards Certification:

None identified

Heritage and History - General Comments:

No Comment.

5 - Sustainability

Certifications:

None

Window Last Replacement:

Never

Weather Stripping:

Not applicable

R Value Roof/Wall:

Not inferable from visual inspection or document search. Wall composition is concrete with limestone veneer as shown on drawing sheet S-6 (1966) with no additional insulation indicated

Systems:

No comment.

Deficiencies:

No comment.