

Zoology Building

D05



[If you have comments, send additional information](#)

Address: 1101 East 57th Street

Year Construction: 1897

Year Acquired: 1897

Architect: Henry Ives Cobb

Gross Square Feet: 39,134

Primary Use: Laboratory

Design Zone: Main Quadrangle

Last Major Renovation:

Piecemeal renovations and reconfigurations

Comments:

Part of Hull Court. Piecemeal renovations and reconfigurations to support research.

REGULATORY STATUS

National Register: Not individually listed

NR Historic District:

Hyde Park-Kenwood Historic District

Chicago HRS Color Code: Orange

1 - Site

Land Ownership Status: Owned

Location - Physical:

Location - Program Adjacency:

Connected to Erman Hall via basement corridor and first floor covered walkway. Connected to Anatomy Hall via covered Cobb Gate.

Location Comment:

Connected to Hull Court building group and has attached underground biological laboratories to the south of the building.

2 - Adaptability

Construction Type:

Load-bearing masonry walls and steel construction

Accessibility:

Entrance - Y; Bathrooms - N

Floor-to-Floor Height:

1st, 2nd, 3rd: 13'-8", 4th: 12'-5"

Structural Capability:

Adaptable subject to structural analysis.

Adaptability Exterior:

Exterior adaptation or addition would require sensitivity to integrity of existing facades.

Adaptability Interior:

Adaptable for similar use within construction type restraints.

Adaptability Physical Features:

No comment

Adaptability Structure:

Adaptable within construction type restraints.

3 - Building Envelope

Roof Type: Clay Tile

Exterior Facade:

Limestone

Exterior Base: Limestone

Exterior Trim: Limestone

4 - Heritage and Historic

Landmark Status:

no

National Register: Not individually listed

NR Historic District:

Hyde Park-Kenwood Historic District

NR Comments:

Architectural significance, item #108 on the district nomination form

CHRS Comments:

Possesses potentially significant architectural or historical features

Heritage - Exterior:

Building is an integral part of the Hull Court architectural grouping. Adaptation or modification should be considered in relation to adjacent buildings.

Heritage - Interior:

Interior contains few original design features except for the main staircase and stone flooring on the first floor.

Significant Spaces Identified:

Zoology Building D05

No Comment

Heritage Culture Elements:

Building office and laboratory spaces have been modified significantly to provide improved facilities.

Architectural Awards Certification:

none identified

Heritage and History - General Comments:

Building has significant visual impact due to its facade and its relationship to Hull Court buildings.

5 - Sustainability

Certifications:

none identified

Window Last Replacement:

1998

Weather Stripping:

not identified

R Value Roof/Wall:

not identified

Systems:

Deficiencies: