



Rivermark
HOME INSPECTIONS

RIVERMARK HOME INSPECTIONS

brandon@rivermarkinspections.com
<https://www.rivermarkinspections.com>

A look inside a
Rivermark report

Fictional findings and illustrations
from our Residential report
template

RESIDENTIAL HOME INSPECTION REPORT

FICTIONAL RESIDENTIAL SAMPLE

No property was inspected for this example.
Illustrations show findings, priorities and limitations.

Inspector
Brandon Wilcox

brandon@rivermarkinspections.com

TABLE OF CONTENTS

1: Inspection Details and Report Guide	5
2: Roof	6
3: Exterior, Site, and Drainage	7
4: Foundation, Basement, Crawlspace, and Structure	8
5: Heating	9
6: Cooling	10
7: Plumbing and Water Heating	11
8: Electrical	12
9: Fireplaces and Chimneys	13
10: Attic, Insulation, Ventilation, and Exhaust	14
11: Interior, Doors, Windows, and Safety Observations	15
12: Built-In Kitchen Appliances	16
13: Garage and Included Detached Structures	17
14: Specialized Systems — Visual Context, When Present	18
15: Inspection Limitations and Follow-Up Overview	19

This report describes a visual, non-invasive inspection of the agreed residential scope on the inspection date. Findings are organized by system, with locations, supporting evidence and recommended next steps. Inspected does not mean defect-free. Read the complete report, including system limitations and the Inspection Limitations and Follow-Up Overview. Significant Concern identifies material safety, functional, structural or active-damage concerns warranting prompt attention. Repair / Further Evaluation identifies conditions needing repair or qualified evaluation. Maintenance / Monitor identifies relevant lower-priority maintenance or monitoring. Priority depends on the actual condition and context; urgent concerns also require direct communication. Onsite comments are preliminary until report review. The report does not guarantee concealed conditions or future performance. Separately contracted ancillary services have their own stated scope and deliverables.

-  2.2.1 Roof - Flashings and Roof Penetrations: Deteriorated Penetration Seal
-  3.5.1 Exterior, Site, and Drainage - Grading, Site Drainage, and Vegetation: Vegetation Contacts Building
-  8.6.1 Electrical - GFCI and AFCI Protection: Protective Device Did Not Trip During Testing

1: INSPECTION DETAILS AND REPORT GUIDE

		IN	LIM	NI	NP	NA
1.1	Inspection Conditions		X			
1.2	Contracted Coverage and Separate Services					X

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

Information


Inspection Conditions: Utilities and Access Context

FICTIONAL SAMPLE - NO REAL CLIENT OR PROPERTY. This fictional exercise uses diagrams and text to illustrate report organization. No utilities or equipment were operated. The example includes a restricted roof view and a separate access limitation so the reader can distinguish an observation from an unknown condition. Unanswered systems are not evidence of inspection, approval, or satisfactory condition. The complete report and its limitations provide context that a priority summary cannot replace. What utility availability, occupancy, storage, access, or preparation conditions materially affected the inspection, and what remained undetermined?

Contracted Coverage and Separate Services: Included Areas and Assignment Limits

FICTIONAL SAMPLE. no inspection of a real property occurred. Which dwelling areas and ordinary included detached structures are within this assignment, and what explicit assignment limits or applicability questions remain?

FICTIONAL SAMPLE



Limitations

Inspection Conditions UTILITY OR ACCESS LIMITATION

FICTIONAL EXAMPLE: A fictional storage barrier limits the example observation area. No actual property or equipment was inspected. The area behind the barrier remains unknown; the example next step is to arrange access and further observation before relying on its condition.

2: ROOF

		IN	LIM	NI	NP	NA
2.1	Roof Coverings			X		
2.2	Flashings and Roof Penetrations					
2.3	Gutters and Downspouts					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

Limitations

Roof Coverings

ROOF SURFACE OBSCURED

FICTIONAL EXAMPLE: The diagram represents an obscured roof surface. The covered area was not inspected in this fictional scenario, and its condition is unknown. The example next step is further evaluation when the surface is safely visible; no favorable condition is inferred.

FICTIONAL SAMPLE



Sample illustration - obscured area remains unknown

Observations

2.2.1 Flashings and Roof Penetrations

DETERIORATED PENETRATION SEAL

FICTIONAL EXAMPLE: The diagram scenario describes a fictional deteriorated roof penetration seal. Its extent and concealed effects are unknown. The example next step is evaluation and appropriate repair by a qualified roofing contractor. No actual roof was inspected.

 Repair / Further Evaluation

3: EXTERIOR, SITE, AND DRAINAGE

		IN	LIM	NI	NP	NA
3.1	Wall Coverings, Trim, and Flashing					
3.2	Exterior Doors and Window Openings					
3.3	Decks, Porches, Balconies, and Carports					
3.4	Exterior Steps, Guards, and Handrails					
3.5	Grading, Site Drainage, and Vegetation	X				
3.6	Adjacent Walkways, Driveways, Patios, and Retaining Walls					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

Observations

3.5.1 Grading, Site Drainage, and Vegetation

 Maintenance / Monitor

VEGETATION CONTACTS BUILDING

FICTIONAL EXAMPLE: The exterior diagram shows a fictional branch touching a wall. The example maintenance step is to keep vegetation clear of the wall so the surface remains visible for routine monitoring. This is a fictional illustration, not a property finding.

FICTIONAL SAMPLE



Sample illustration - fictional exterior diagram

4: FOUNDATION, BASEMENT, CRAWLSPACE, AND STRUCTURE

		IN	LIM	NI	NP	NA
4.1	Foundation and Basement					
4.2	Crawlspace					
4.3	Floor Framing and Supports					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

5: HEATING

		IN	LIM	NI	NP	NA
5.1	Heating Equipment and Controls					
5.2	Heating Distribution					
5.3	Heating Venting and Combustion-Related Observations					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

6: COOLING

		IN	LIM	NI	NP	NA
6.1	Cooling Equipment and Controls					
6.2	Cooling Distribution					
6.3	Cooling Condensate Management					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

7: PLUMBING AND WATER HEATING

		IN	LIM	NI	NP	NA
7.1	Water Source, Service, and Main Shutoff					
7.2	Water Supply Distribution and Static Pressure					
7.3	Fixtures, Toilets, and Functional Flow					
7.4	Drain, Waste, and Vent					
7.5	Water-Heating Equipment and Temperature					
7.6	Water-Heater Venting and Safety Components					
7.7	Visible Fuel Storage, Piping, and Main Shutoff					
7.8	Sump Pumps and Backup Systems					
7.9	Sewage Ejectors					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

8: ELECTRICAL

		IN	LIM	NI	NP	NA
8.1	Service Entrance, Meter, and Main Disconnect					
8.2	Panels and Overcurrent Protection					
8.3	Visible Grounding and Bonding					
8.4	Visible Branch Wiring and Connections					
8.5	Accessible Receptacles, Switches, and Lighting					
8.6	GFCI and AFCI Protection					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

Observations

8.6.1 GFCI and AFCI Protection

PROTECTIVE DEVICE DID NOT TRIP DURING TESTING

 Significant Concern

FICTIONAL EXAMPLE: The electrical diagrams illustrate a fictional protective device that does not respond to its built-in test control. No live device was tested. In this example the intended protective function remains unverified; avoid relying on that protection and arrange evaluation by a qualified electrician before use. This is not an electrical safety certification.

FICTIONAL SAMPLE

ELECTRICAL - DETAIL



TEST DIAGRAM - NO REAL PROPERTY

Fictional shapes only. Not inspection evidence.

Sample illustration - fictional electrical detail

FICTIONAL SAMPLE

ELECTRICAL - CONTEXT



TEST DIAGRAM - NO REAL PROPERTY

Fictional shapes only. Not inspection evidence.

Sample illustration - fictional electrical context

9: FIREPLACES AND CHIMNEYS

		IN	LIM	NI	NP	NA
9.1	Firebox, Hearth, Damper, and Cleanout					
9.2	Chimney Exterior and Visible Venting					
9.3	In-Service Gas Fireplace Controls					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

10: ATTIC, INSULATION, VENTILATION, AND EXHAUST

		IN	LIM	NI	NP	NA
10.1	Attic Access and Visible Roof Framing					
10.2	Visible Insulation and Representative Depth					
10.3	Attic and Unfinished-Area Ventilation					
10.4	Kitchen, Bathroom, and Laundry Exhaust Paths					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

11: INTERIOR, DOORS, WINDOWS, AND SAFETY OBSERVATIONS

		IN	LIM	NI	NP	NA
11.1	Floors, Walls, Ceilings, Counters, and Cabinets					
11.2	Accessible Interior and Exterior Doors					
11.3	Accessible Windows					
11.4	Stairs, Landings, Ramps, Guards, and Handrails					
11.5	Visible Glazing and Other Interior Safety Conditions					
11.6	Smoke and Carbon-Monoxide Alarms					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

12: BUILT-IN KITCHEN APPLIANCES

		IN	LIM	NI	NP	NA
12.1	Range and Cooktop					
12.2	Oven					
12.3	Dishwasher					
12.4	Food-Waste Disposal					
12.5	Built-In Microwave					
12.6	Range Hood and Kitchen Exhaust					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

13: GARAGE AND INCLUDED DETACHED STRUCTURES

		IN	LIM	NI	NP	NA
13.1	Garage-to-Dwelling Separation and Entry Door					
13.2	Overhead Doors, Openers, and Safety Features					
13.3	Garage Foundation, Floor, and Visible Framing					
13.4	Detached Garage Roof, Enclosure, Openings, and Site					
13.5	Detached Garage Electrical and Other Included Systems					
13.6	Included Ordinary Storage Shed — Limited Visual Observation					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

14: SPECIALIZED SYSTEMS — VISUAL CONTEXT, WHEN PRESENT

		IN	LIM	NI	NP	NA
14.1	Solar, Standby Generator, and EV Equipment — Visual Context					
14.2	Water Treatment and Central Vacuum — Visual Context					
14.3	Fire Sprinklers, Security, Lifts, Saunas, and Similar Systems — Visual Context					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable

15: INSPECTION LIMITATIONS AND FOLLOW-UP OVERVIEW

		IN	LIM	NI	NP	NA
15.1	Material Limitations and System References					
15.2	Pending Contracted Deliverables and Follow-Up Questions					

IN = Inspected LIM = Material limitation NI = Not inspected NP = Not present NA = Not applicable