
N
Building 9B door
low, −1.2 dB
→ medium, 5.7 dB
Bike rack
medium, 8.6 dB
Staging
(recovery point)
gNB (n40)
Bus stop
low, −1.3 dB
→ medium, 2.9 dB
50 m
Footpath coverage
good
medium
low
lost
exposed post
relocated post