
view_frames Result
Recorded at time: 1778492609.3444197
base_footprint
Broadcaster: default_authority
Average rate: 10000.0
Buffer length: 0.0
Most recent transform: 0.0
Oldest transform: 0.0
base_link
Broadcaster: default_authority
Average rate: 10000.0
Buffer length: 0.0
Most recent transform: 0.0
Oldest transform: 0.0
Broadcaster: default_authority
Average rate: 13.535
Buffer length: 4.95
Most recent transform: 1778492609.332217
Oldest transform: 1778492604.382225
Broadcaster: default_authority
Average rate: 13.535
Buffer length: 4.95
Most recent transform: 1778492609.332217
Oldest transform: 1778492604.382225
Broadcaster: default_authority
Average rate: 13.535
Buffer length: 4.95
Most recent transform: 1778492609.332217
Oldest transform: 1778492604.382225
Broadcaster: default_authority
Average rate: 13.535
Buffer length: 4.95
Most recent transform: 1778492609.332217
Oldest transform: 1778492604.382225
lidar_link
front_left_steering_link
front_right_steering_link
rear_left_wheel_link
rear_right_wheel_link
Broadcaster: default_authority
Average rate: 13.535
Buffer length: 4.95
Most recent transform: 1778492609.332217
Oldest transform: 1778492604.382225
Broadcaster: default_authority
Average rate: 13.535
Buffer length: 4.95
Most recent transform: 1778492609.332217
Oldest transform: 1778492604.382225
front_left_wheel_link
front_right_wheel_link