

view_frames Result

Recorded at time: 1778337727.3534408

base_footprint

Broadcaster: default_authority
Average rate: 10000.0
Buffer length: 0.0
Most recent transform: 0.0
Oldest transform: 0.0

base_link

Broadcaster: default_authority
Average rate: 15.4
Buffer length: 5.0
Most recent transform: 1778337727.3408
Oldest transform: 1778337722.340793

Broadcaster: default_authority
Average rate: 15.4
Buffer length: 5.0
Most recent transform: 1778337727.3408
Oldest transform: 1778337722.340793

Broadcaster: default_authority
Average rate: 15.4
Buffer length: 5.0
Most recent transform: 1778337727.3408
Oldest transform: 1778337722.340793

Broadcaster: default_authority
Average rate: 15.4
Buffer length: 5.0
Most recent transform: 1778337727.3408
Oldest transform: 1778337722.340793

front_left_steering_link

front_right_steering_link

rear_left_wheel_link

rear_right_wheel_link