## Inspections Today

Vehicle Type	Chassis Number	Engine Number	Body Condition	Glass & Indicat	o <b>Ti</b> res & Wheel	Engine Condition	Transmission & Ge	ട്ടിയാpension & Stee	Bingaking System
EV Cars	1HGCM82633A12	5 <b>4,56</b> 2345U123457I	Good	Good	Good	Good	Good	Good	Good
EV Cars	1HGCM82633A12	<b>374,56</b> 2345U123456I	Good	Good	Good	Poor	Good	Good	Good
EV Buses	1HGCM82633A12	3 <b>74.67</b> 2345U123467I	Good	Good	Good	Good	Good	Good	Good