

TUV India Control No: (SAP Number)	010101081825/107 (8123516835)	Date:	05/01/2026
Project Name & Location:	Top Side Facility 3rd Berth (Jetty) , Dahej Gujrat PDEP Project	TUV India Branch Name:	Chennai
TUV India Client Name:	TOYO ENGINEERING INDIA PRIVATE LIMITED	End User Name:	Petronet LNG Limited (PLL)
DEC / PMC / EPC Name: (If applicable)	Engineers India Limited (EIL)	DEC / PMC / EPC Assignment Number: (If applicable)	B940
Vendor Name & Location:	BERGEN PIPE SUPPORTS (INDIA) PVT. LTD.	P.O. Number: (Client PO on Vendor)	P/6471/63457/AXHH003B-1 Dated 19/09/2025
Sub Vendor Name & Location: (If applicable)		P.O. Number: (If applicable - Vendor PO on Sub Vendor)	

Item Description:

PO Item No.	Item Code	Item Description / Identification / MTC Number	UOM	P.O. Quantity	Offered Quantity	Accepted Quantity	Cumulative accepted Quantity
3	ID3250203A3	CRADLE Supports SIZE: 3" TAG Number:G-3-250-203-A.	Piece	4	4	4	4
24	IG3250202B3	CRADLE Supports SIZE: 3" TAG Number:G-3-250-202-B	Piece	5	4	4	4
25	IG3350202A3	CRADLE Supports SIZE: 3" TAG Number:G-3-350-202-A	Piece	4	3	3	3
26	IG3400202A3	CRADLE Supports SIZE: 3" TAG Number:G-3-400-202-A	Piece	10	7	7	7
44	IPRD3250203A3	CRADLE Supports SIZE: 3" TAG Number:PR-D-3-250-203-A	Piece	2	1	1	1
47	IPRD6300203A6	CRADLE Supports SIZE: 6" TAG Number:PR-D-6-300-203-A	Piece	1	1	1	1
49	IPRG1.5250202A1	CRADLE Supports SIZE: 1.5" TAG Number:PR-G-1.5-250-202-A	Piece	2	2	2	2
50	IPRG2250202A2	CRADLE Supports SIZE: 2" TAG Number:PR-G-2-250-202-A	Piece	3	3	3	3
54	IPRG3250202B3	CRADLE Supports SIZE: 3" TAG Number:PR-G-3-250-202-B	Piece	1	1	1	1

Disclaimer: The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Release Note / Certificate does not relieve Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way/ legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Private Limited and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TUV NORD GROUP): (REGD. & HEAD OFFICE)
 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai - 400086, Maharashtra, India.
 Tel: + 91 22 66477000, Email: inspection@tuv-nord.com Website: www.tuv-nord.com/in
 Form No.: F / INSP / IRN / 03 - R08 / TIMES; Revision Date: 27.10.2023

56	IPRG4250202A4	CRADLE Supports SIZE: 4" TAG Number:PR-G-4-250-202-A	Piece	4	3	3	3
57	IPRG6300202A6	CRADLE Supports SIZE: 6" TAG Number:PR-G-6-300-202-A	Piece	4	4	4	4
60	IPRR2250201A2	CRADLE Supports SIZE: 2" TAG Number:PR-R-2-250-201-A	Piece	8	5	5	5
66	IPRR4250201A4	CRADLE Supports SIZE: 4" TAG Number:PR-R-4-250-201-A	Piece	2	2	2	2
67	IPRR6300201A6	CRADLE Supports SIZE: 6" TAG Number:PR-R-6-300-201-A	Piece	3	3	3	3
68	IPRVD3250208A3	CRADLE Supports SIZE: 3" TAG Number:PR-VD-3-250-208-A	Piece	6	3	3	3
72	IR2250201A2	CRADLE Supports SIZE: 2" TAG Number:R-2-250-201-A	Piece	20	5	5	19
86	IVD2250208A2	CRADLE Supports SIZE: 2" TAG Number:VD-2-250-208-A	Piece	2	2	2	2
87	IVD3250208A3	CRADLE Supports SIZE: 3" TAG Number:VD-3-250-208-A	Piece	14	9	9	9

Reference Documents:

Sr. No.	Document Name	Client Document Number	Vendor Document Number	Approval Status
1	PR/MR/ARM	6471-PIP-MPR-AXHH003	Not Applicable	Issued by TOYO
2	QAP/ITP/QCP	PDEP-VD-TFTJ-PIP-AXHH003-ITP-0001 Rev.01	6471-T-BPSI-TH-AXHH003-0005 Rev.01 (ITP Number: CG036601/ITP/01 Rev.01)	CODE-1 (TOYO & TUV)
3	Drawing(s)	PDEP-VD-TFTJ-PIP-AXHH003-ARG-0003 Rev.03	6471-T-BPSI-TH-AXHH003-0002 Rev.03.	CODE-1 (TOYO)
4	Datasheet(s)	Not Applicable	Not Applicable	Not Applicable
5	Procedure(s)	PDEP-VD-TFTJ-PIP-AXHH003-PP-0002- 002 Rev.00 PDEP-VD-TFTJ-PIP-AXHH003-PRC-0001 Rev.01 PDEP-VD-TFTJ-PIP-AXHH003-PRC-0003 Rev.01	6471-T-BPSI-TH-AXHH003-0004 Rev.00 - Coating Procedure 6471-T-BPSI-TH-AXHH003-0003 Rev.01 - WPS/PQR]6471-T-BPSI-TOYO-1-AXHH003-0008 Rev.01 - LPT Procedure	CODE-1 by (TOYO) CODE-1 (TOYO & TUV) CODE-1 (TOYO & TUV)

Disclaimer: The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Release Note / Certificate does not relieve Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way/ legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Private Limited and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TUV NORD GROUP): (REGD. & HEAD OFFICE)
 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai - 400086, Maharashtra, India.
 Tel: + 91 22 66477000, Email: inspection@tuv-nord.com Website: www.tuv-nord.com/in
 Form No.: F / INSP / IRN / 03 - R08 / TIMES; Revision Date: 27.10.2023

6	Others(Specify)	Not Applicable	Not Applicable	Not Applicable
---	-----------------	----------------	----------------	----------------

Stages Witnessed:

- 1) Random witnesses 10% PMI Inspection carried out selected Witnessed Item from the over all Offered cradle Support protection shield, Thrust rings and sliding plates PMI checked and meets as per the Material standard Requirements and found acceptable.
- 2) Witnessed 100% final Weld and Visual Inspection carried out for offered Cradle Supports with Assembled Condition No Surface Defects observed and found satisfactory.
(Total offered Quantity : 62 No's.)
- 3) Random witnesses 10% Final Dimension Inspection carried out selected Witnessed Item from the over all Offered cradle Support with Assembled condition Dimension checked with respect to Drawing and found satisfactory
- 4) Random witnesses 10% Surface Coating Thickness Inspection carried out selected Witnessed Item from the overall Offered cradle Supports with Assembled condition DFT Checked at Random Location with respect to the Approved Procedure and found satisfactory.
- 5) Random witnesses 10% Marking Identification Inspection checked with respect to the Drawing Checked and found Satisfactory
- 6) Random witnesses 10% Checked the all Ancillaries with respect to the Drawing and found satisfactory.

Documents Reviewed:

- 1) Reviewed the Photocopy of MTC for Carbon steel Plate Checked Chemical Composition and Mechanical Properties Values meets the Material Standard Requirements and found in order.
- 2) Reviewed the Photocopy of MTC for Bolt/Stud, NUT & Washer Checked Chemical Composition and Mechanical Properties Values meets the Material Standard Requirements and found in order.
- 3) Reviewed the Photocopy of MTC for Stainless steel Sheet/Plates Checked Chemical Composition and Mechanical Properties Values meets the Material Standard Requirements and found in order.
- 4) Reviewed the EN 10204 2.1 COC for SEALANT AND ADHESIVE, PROTECTION SHIELD & VAPOUR BARRIER FOIL Checked and found in order.
- 5) Reviewed the Weld visual Inspection Reports checked and found in order.
- 6) Reviewed the DPT Inspection Reports checked and found in order.
- 7) Reviewed the PMI Inspection Reports for Protection shield plate, thrust ring, and Sliding Plate checked and found in order.
- 8) Reviewed the Coating Inspection Reports checked and found in order.
- 9) Reviewed the EN 10204 2.1 Production batch Certificate for HD PUF Ultimate Compressive strength Reports Checked with Respect to TABLE.1. SI.No.1.1. Acceptance criteria given and found in order.
Reviewed the EN 10204 2.1 Production batch Certificate for HD PUF Core Density Reports Checked with Respect to TABLE.1 . SI.No.1.2. Acceptance criteria given and found in order.
- 10) Reviewed the Pre-Shipment reports checked and found in order.
- 11) Reviewed the Compilation of Quality Documents checked with respect to ITP and Drawing found in order.
- 12) Reviewed the Ultimate Compressive strength for density of 160 kg/m³, 240 kg/m³ and 320 kg/m³ @ 23 Degree C Reports Checked and found in order.
Reviewed the Core density of 160 kg/m³, 240 kg/m³ and 320 kg/m³ @ 23 Degree C Reports Checked and found in order.
- 13) Reviewed the Thermal Conductivity for density of 160 kg/m³, 240 kg/m³ and 320 kg/m³ @ -165 Degree C & Room Temperature Checked as per ASTM D1621 Meets and Found Satisfactory.
Reviewed the Ultimate Compressive Strength for density of 160 kg/m³, 224 kg/m³ and 320 kg/m³ @ -165 Degree C & Room Temperature Checked as per ASTM D1621 Meets and Found Satisfactory.
Reviewed the Linear Coefficient of Expansion for Density of 160 kg/m³, 224 kg/m³ and 320 kg/m³ @ -165 Degree C to Room Temperature Checked as per D696 Meets and Found Satisfactory.
- 14) Verified Calibration status of instruments used during inspection – Found within calibrated due date.

NCR / Waiver: (If Any)

None.

Identification:

Verified Identification Marking with Manufacturer Name Plate

Order status:☐ Complete ☒ Incomplete

Disclaimer: The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Release Note / Certificate does not relieve Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way/ legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Private Limited and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TUV NORD GROUP): (REGD. & HEAD OFFICE)
 801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai - 400086, Maharashtra, India.


Tel: + 91 22 66477000, Email: inspection@tuv-nord.com Website: www.tuv-nord.com/in

Form No.: F / INSP / IRN / 03 - R08 / TIMES; Revision Date: 27.10.2023

Page: 3 of 4

Date(s) of Inspection: , 31/12/2025,02/01/2026

Conclusion: All items were inspected within the scope defined in PO, approved QAP/ITP/QCP & specifications - found to meet the specified requirements. .



MANIVASAGAM K

Surveyor(S) to TUV India Private Limited

Scan For Verification



(Code Valid For 1 Year)

Distribution List: ☒ TUVI Client / End User ☒ TUV Executing Branch / TUV Originating Branch ☒ Vendor / Sub Vendor

Revision Number (If Applicable) [0] : -

This Document Supersedes IRN No.: -

Disclaimer: The inspection by TUV India Pvt. Ltd., review of Test Certificates / Reports and issue of Inspection Release Note / Certificate does not relieve Client / Supplier / Manufacturer / Stockiest from their responsibility towards the Client / End User to supply the genuine material / item(s) and document(s) in full compliance with applicable Order, Specification, Technical, Quality, Quantity, Warranty, Guarantee requirements. Supplier / Manufacturer / stockiest is wholly legally responsible for genuineness of the material / item(s) supplied and document(s) submitted. TUV India's responsibility is only limited to correctness of inspection results including review of the documents, within its agreed scope against written requirements and neither TUV India nor any of its group companies, associates or employees are in any way/ legally responsible for genuineness of the material / item(s) and document(s). If the calibration certificate(s) for the measuring instrument(s) / equipment(s) used during inspection do not have traceability to NABL / Other certifying bodies, then the scope of review is limited only to technical content in the calibration certificate.

Copyright: This document is the property of TUV India Private Limited and should not be reproduced, except in full without the consent of TUV India Pvt. Ltd.

TUV India Pvt. Ltd. (TÜV NORD GROUP): (REGD. & HEAD OFFICE)
801, Raheja Plaza - I, LBS Marg, Ghatkopar (West), Mumbai - 400086, Maharashtra, India.

Tel: + 91 22 66477000, Email: inspection@tuv-nord.com Website: www.tuv-nord.com/in

Form No.: F / INSP / IRN / 03 - R08 / TIIMES; Revision Date: 27.10.2023

Page: 4 of 4