

Final Inspection

Inspection #: 1278753, 1278754, 1278755,
1278756, 1278757, 1278758, 1278759, 1278760,
1278761, 1278762, 1278763, 1278764, 1278765,
1278766 | Group #: 118994

Inspection Details

Scheduled Inspection Date		Inspection Started Date		Submitted Inspection Date	
2025-02-24 08:00		2025-03-05 07:36		2025-03-13 10:58	
Report Type	Final Inspection	Project	ARITZIA		
Inspector	Sok Layheang	Supplier	YM		
Total PO Items Qty	5,651	Sample Inspected	200		
Factory Name	YM	Approved By	heng		
Created Date	2025-02-21	Submitted Inspection Date	2025-03-13		
Last Modified Date	2025-03-15				
PO #	GPAR11387	ETD	2025-03-27		
Destination	GROVEPORT, Toronto, Vancouver	Supplier ERP ID	YM		
SKU #	FFS 99-03-32366-SU25-AR001-63219-106-CAN, FFS 99-03-32366-SU25-AR001-63219-72-CAN, FFS 99-03-32366-SU25-AR002-63219-106-CAN, FFS 99-03-32366-SU25-AR002-63219-72-CAN, FFS 99-03-32366-SU25-AR4250-63219-106-CAN, FFS 99-03-32366-SU25-AR4250-63219-72-CAN, FFS 99-03-32366-SU25-AR4290-63219-106-CAN, FFS 99-03-32366-SU25-AR4290-63219-72-CAN, FFS 99-03-32366-SU25-ARH106-63219-106-CAN, FFS 99-03-32366-SU25-ARH106-63219-140-USA, FFS 99-03-32366-SU25-ARH106-63219-72-CAN, FFS 99-03-32366-SU25-ARH300-63219-106-CAN, FFS 99-03-32366-SU25-ARH300-63219-140-USA, FFS 99-03-32366-SU25-ARH300-63219-72-CAN	Description	LADIES' 78% COTTON 22% POLYESTER KNITTED SWEATSHIR		
Style	FFS 99-03-32366-SU25	Color	BLACK [QTY : 401], BLACK [QTY : 599], HEATHER CHROME [QTY : 249],		

		HEATHER CHROME [QTY : 401], HEATHER CHROME [QTY : 602], HEATHER CLOUD WHITE [QTY : 200], HEATHER CLOUD WHITE [QTY : 360], HEATHER CLOUD WHITE [QTY : 539], VILLA PINK [QTY : 240], VILLA PINK [QTY : 360], VINTAGE NAVY [QTY : 280], VINTAGE NAVY [QTY : 420], WHITE [QTY : 400], WHITE [QTY : 600]	
Season	S5/2025	Ship Mode	SEA
Inspected Qty (Pcs)	5,651	Master Carton / Packed Quantity (Ctns)	259
Inspected Carton Numbers	PO#1639: 1,16,1,6,13,11,10, PO#1638: 52,58,90,82,99,10 7,48,62, PO#1637: 77,75,38,4 7,43,16,71,32,35,29,14,31,19, 65,41,20,23,12,60,1,17, PO#1637: 7,1,18 (air), PO#1638: 1 4,15 (air)		

Conclusion

Inspection Result	PASS	Approval Status	Accepted
Checklists			PASS
Packing, Packaging & Labelling			PASS
Workmanship			PASS
Quality Plan (Quality Plan尺寸表 - ARITZIA)			PASS

Inspection Duration (Mins)	68.21
----------------------------	-------


Comments

Due inspection final before scan
 Carton dimension 60.96 x 50.8 x 25.4 cm
 Gross weight 5.80 to 13.50 kg
 Remark: finish pack ctn
 Qty: 233ctn=5085pcs
 Iron: 100%
 QC: 100%
 Pack: 100%

 The inspector confirmed that the answers contained in this report have been answered to the best of their knowledge and all sections have been completed.


Severity of Defects

Minor: 0.0 % Critical: 0.0 %



Highcharts.com

Pareto Defects



Highcharts.com

Checklists

Order Type	Repeat Order	Samples Available?	Yes
Lab Analysis & Testing	Conform	Master Carton Requirements?	Conform
Drop Test?	N/A	Price?	Conform
Hang Tags?	Conform	Labels?	Conform
Composition	Conform		

Qty Conform	8	Qty Non-Conform	0
-------------	---	-----------------	---

Photos

Packing, Packaging & Labelling


Sampling Carton




Shipping Mark - 1




Shipping Mark - 2



Shipping Mark - 3



Shipping Mark - 4



Packed Into Carton



Inner Pack



UPC




Main Label - Size Label Placement



Care Label



Other



Product

Product View - Front



Product View - Back



Compare Sample vs. Actual - Front



Compare Sample vs. Actual - Back



Compare Sample vs. Actual - color Combo 1



Compare Sample vs. Actual - color Combo 2



Compare Sample vs. Actual - color Combo 3



Other



Other



Other



Others


Photos photos 1



Photos photos 2




Photos photos 3




Photos photos 4




Photos photos 5



Photos photos 6



Photos photos 7




Photos photos 8



Photos photos 9



Photos photos 10



Photos photos 11



Photos photos 12




Photos photos 13




Photos photos 14




Photos photos 15




Photos photos 16




Photos photos 17



Photos photos 18



Photos photos 34



Photos photos 35



Packing, Packaging & Labelling

Sample Size & AQL

Inspection Method	Inspection Level	Critical	Major	Minor	Carton Qty	Sample Size (Ctns)
normal	II	0.010	1.500	0.010	259	32

Section Conclusion

	Critical	Major	Minor
Total Defects	0	0	0
Accept/Reject Qty	0/1	1/2	0/1

Total Defective Units	0	Inspection Result	PASS
-----------------------	---	-------------------	------

Inspected Carton Numbers

Qty of Cartons Scanned: 5

PO#1639: 1,16,1,6,13,11,10	PO#1638: 52,58,90,82,99,10 7,48,62	PO#1637: 77,75,38,47,43,16, 71,32,35,29,14,31,19,65,41,2 0,23,12,60,1,17	PO#1637: 7,1,18 (air)
PO#1638: 14,15 (air)			

Workmanship

Sample Size & AQL

Inspection Method	Inspection Level	Critical	Major	Minor	Qty Inspected	Sample Inspected
normal	II	0.010	1.500	0.010	5,651	200

Section Conclusion

	Critical	Major	Minor
2-Stitching-Needle holes	0	1	0

2-Stitching-Stitches: Uneven	0	1	0
3-workmanship-Collar: Poor setting	0	1	0
3-workmanship-Slanted/Uncentered	0	1	0
Total Defects	0	4	0
Accept/Reject Qty	0/1	7/8	0/1

Total Defective Units	4	Inspection Result	PASS
E-Sewing & Linking			

2-Stitching-Needle holes (E-13)

Defect Severity	Quantity	Comment
Major	1	Hole at sleeve

IMAGE Image 1



2-Stitching-Stitches: Uneven (E-21)

Defect Severity	Quantity	Comment
Major	1	

IMAGE Image 1



Uneven placement at EMB

3-workmanship-Collar: Poor setting (E-29)

Defect Severity	Quantity	Comment
Major	1	

IMAGE Image 1



Poor neck shape

3-workmanship-Slanted/Uncentered (E-35)

Defect Severity	Quantity	Comment
Major	1	

IMAGE Image 1



Half moon off centre

Quality Plan (Quality Plan尺寸表 - ARITZIA) 

Total Defective Units	0	Inspection Result	PASS
Measurement 尺寸表			PASS
Sample Size & AQL			
Inspection Method	Inspection Level	Qty Inspected	Sample Inspected
N/A	N/A	5,651.00	1.00
Question	Status	Fail Qty	Comment
Is Measurement OK?	Pass	0	