

CMHGIC01

VEHICLE / PLANT WEED HYGIENE INSPECTION CERTIFICATE

Company Name

MPC Kinetic

Operating For

Origin Energy

Operation Area

Melb

Vehicle Type

Generic Vehicle/Plant

Vehicle ID

4123123 HC

Asset ID

000 999

Inspection date: 2022-09-11 Date Expiry: 2023-01-12

Make

Toyota

Model

2

Odometer

12

Undercarriage?

(if Applicable)

- Chassis Rails
- Wheels & tyres (incl. spares)
- Wheel arches
- Tyre rims
- Axles/Diffs
- Mud flaps
- Suspension
- Tracks, rollers and track frame
- Stabilisers & stands

External Areas

(if Applicable)

- Grill
- Wiper recess
- Gear box
- Radiator
- Engine bay
- Side steps

- Bumper bar / counterweight
- Tray
- Toolboxes & batteries
- Fuel tank guards
- Tow point / draw bar
- Winches, ropes & slings
- Hydraulic & electric cables/connections
- Saddle bags
- Tarpaulins & tarpaulin canopies
- Camoflauge nets
- Light assembly
- Power pack & power pack bay
- Driver crash pad (& removed)
- Ventilation fans/air ducts
- Propellor housing
- Evaporator housing filters
- Air filter assembly
- Drain
- Row units
- Man basket
- Buckets, blades, scoops, scrapes, tines
- Telescopic boom/mast/ladder
- Farming accessories (inc. rotary hoe, sprayer, seeder, ripper, baler, mower etc.)
- Hoses/valves
- Slingers/Tubs/Piping/Pumps

Internal Areas

(if Applicable)

- Cabin
- Housing
- Boot
- Attachment/Load/Other

Comments

declare that this vehicle has been inspected and deemed not clean and free of organic material.



Inspected and verified by:

Inspector Name: inspector Phone Number: Inspector Certification Number: Inspection Location:

Inspector 1
Inspec

Bonkaasd 4242442 Tesla

Conditions:

With a verified vehicle / plant inspection certificate, the driver/operator is authorised to enter worksites as long as a valid copy of this report is kept within the vehicle and/or mobile plant. This report shall be available to view upon request in the CertMate application or if printed.

This report may be declared void if any land owner or authorised representative of land owner declares that the vehicle/mobile plant can no longer be deemed to be clean and free from organic materials. This report remains valid as long as the following conditions are met:

- 1. The Vehicle and/or Mobile Plant does not travel off formed roads.
- 2. The Vehicle and/or Mobile Plant if operating off road stays within the designated work area.
- 3. The Vehicle and/or Mobile Plant does not come into direct contact with declared weeds.
- 4. The driver/operator does not operate the Vehicle and/or Mobile Plant after coming into direct contact with declared weeds.



This Vehicle / Plant Inspection Certificate has been created [21:13 / 2022-11-15] by Aevi Tech Pty Ltd and stored in the CertMate Cloud Server (Terms & Conditions available in CertMate application).Document uncontrolled when printed.