

| Asset_ID | Name | Serial_number | Model_number | Model_name | Manufacturer | Installation_date | Warranty_expires | Facility | Building | Floor | Department | Scrapping_date | Data_sheet |
|----------|---------------------------|---------------|-------------------|--|-----------------|-------------------|------------------|----------------|----------|-------|-------------------------------------|----------------|----------------------------------|
| 1 | Syringe pump | 2100587 | SPLF2 | MO-SPLF2 | Holmark | 2019-02-01 | 2024-02-01 | Cairo hospital | 1 | 1 | ICU | 0000-00-00 | Syringe pump_1.pdf |
| 2 | Electric ICU Bed | 3140687 | AG-BY003C | AG-BY003C | AEgEA | 2016-10-08 | 2021-10-08 | Cairo hospital | 1 | 1 | ICU | 0000-00-00 | Electric ICU Bed_2.pdf |
| 3 | Defibrillator | 5170687 | M4735A | Heart start XL | Philips | 2014-03-01 | 2022-03-01 | Cairo hospital | 1 | 1 | ICU | 0000-00-00 | Defibrillator_3.pdf |
| 4 | CT scanner | 6150487 | CT6000ICT | CT6000ICT | Philips | 2015-05-17 | 2026-05-17 | Cairo hospital | 2 | 1 | Radiology | 0000-00-00 | CT scanner_4.pdf |
| 5 | MRI Machine | 9145687 | Siemens Aera 1.5T | Siemens Aera 1.5T | Siemens | 2014-07-01 | 2027-07-01 | Cairo hospital | 2 | 1 | Radiology | 0000-00-00 | MRI Machine_5.pdf |
| 6 | 3D-4D Ultrasound | 2175987 | SAX8LV-EXP | Sonoae X8 | Samsung | 2018-04-07 | 2023-04-07 | Cairo hospital | 3 | 2 | Obstetrics and Gynecology | 0000-00-00 | 3D-4D Ultrasound_6.pdf |
| 7 | 3D-4D Ultrasound | 3140954 | USS-SAR7C3U | Sonoace R7 | Samsung | 2019-08-03 | 2024-08-03 | Cairo hospital | 3 | 2 | Obstetrics and Gynecology | 0000-00-00 | 3D-4D Ultrasound_7.pdf |
| 8 | CARDIOHELP | 5320187 | | CARDIOHELP System | MAQUET | 2013-04-20 | 2018-04-10 | Cairo hospital | 2 | 1 | Cardiology | 2020-04-20 | CARDIOHELP_8.pdf |
| 9 | Tourniquet | 6740587 | 4000 | A.T.S.4000 Tourniquet Systems | zimmer Biomet | 2017-10-01 | 2024-10-01 | Cairo hospital | 3 | 1 | Operating Theater | 0000-00-00 | Tourniquet_9.pdf |
| 10 | Heart-Lung machine | 5940687 | HL 20 | HL 20 Vario Flex | MAQUET | 2013-05-21 | 2020-05-21 | Cairo hospital | 3 | 1 | Operating Theater | 0000-00-00 | Heart-Lung machine_10.pdf |
| 11 | Ventilator | 8957157 | SVM950 | Servo-i Ventilator | MAQUET | 2012-05-19 | 2016-05-19 | Cairo hospital | 1 | 1 | ICU | 0000-00-00 | Ventilator_11.pdf |
| 12 | Vital signs monitor | 2009807 | VS30 | EarlyVue | Philips | 2019-09-08 | 2022-09-08 | Cairo hospital | 3 | 3 | ICU | 0000-00-00 | Vital signs monitor_12.pdf |
| 13 | Electric steam sterilizer | 2190787 | SCF284/03 | Philips Avent 3-in-1 electric steam sterilizer | Philips | 2017-04-11 | 2020-04-11 | Cairo hospital | 1 | 2 | Central sterile services department | 0000-00-00 | Electric steam sterilizer_13.pdf |
| 14 | Anesthesia Machine | 9812345 | GDOA847 | GE Datex Ohmeda Aisys | Soma Tech Intl | 2020-03-18 | 2022-03-18 | Cairo hospital | 3 | 1 | Operating Theater | 0000-00-00 | Anesthesia Machine_14.pdf |
| 15 | Cardiograph | 5463127 | TC70 | PageWriter | Philips | 2017-05-06 | 2019-05-06 | Cairo hospital | 2 | 2 | Cardiology | 0000-00-00 | Cardiograph_15.pdf |
| 16 | Electrosurgical unit | 6100487 | Shark II | Bovie Aaron Smoke Shark II | Soma Tech Intl | 2014-07-13 | 2016-07-13 | Cairo hospital | 3 | 1 | Operating Theater | 0000-00-00 | Electrosurgical unit_16.pdf |
| 17 | Vital signs monitor | 6172487 | 863283 | VS4 | Philips | 2018-03-02 | 2021-03-02 | Cairo hospital | 3 | 3 | ICU | 0000-00-00 | Vital signs monitor_17.pdf |
| 18 | Vital signs monitor | 6936487 | 863283 | VS4 | Philips | 2020-04-02 | 2023-04-02 | Cairo hospital | 3 | 3 | ICU | 0000-00-00 | Vital signs monitor_17.pdf |
| 19 | Vital signs monitor | 9385487 | 67NCTX-B | Connex 6700 | Welch Allyn | 2017-10-02 | 2020-10-02 | Cairo hospital | 3 | 3 | ICU | 0000-00-00 | Vital signs monitor_19.pdf |
| 20 | Electric ICU Bed | 3040687 | ES-96HD | ES-96HD | JosonCare | 2018-10-20 | 2023-10-20 | Cairo hospital | 1 | 1 | ICU | 0000-00-00 | Electric ICU Bed_20.pdf |
| 21 | Electric ICU Bed | 3040649 | ES-96HD | ES-96HD | JosonCare | 2018-11-15 | 2023-11-15 | Cairo hospital | 1 | 1 | ICU | 0000-00-00 | Electric ICU Bed_20.pdf |
| 22 | Electric ICU Bed | 8360649 | ES-12DW | ES-12DW | JosonCare | 2017-02-15 | 2022-02-15 | Cairo hospital | 1 | 1 | ICU | 0000-00-00 | Electric ICU Bed_22.pdf |
| 23 | Ventilator | 9134729 | 980 | Puritan Bennett 980 | Puritan Bennett | 2017-08-19 | 2021-08-19 | Cairo hospital | 1 | 1 | ICU | 0000-00-00 | Ventilator_23.pdf |
| 24 | Ventilator | 9705255 | Newport_HT70_Plus | HT70 | Covidien | 2018-01-01 | 2022-01-01 | Cairo hospital | 1 | 1 | ICU | 0000-00-00 | Ventilator_24.pdf |
| 25 | 3D C-Arm | 2800649 | ARCADIS Orbic 3D | 3000T | Siemens | 2017-02-15 | 2022-02-15 | Cairo hospital | 2 | 1 | Radiology | 0000-00-00 | 3D C-Arm_25.pdf |
| 26 | Portable X-Ray | 1362149 | Optima | XR200MAX | Philips | 2016-03-01 | 2020-03-01 | Cairo hospital | 2 | 1 | Radiology | 0000-00-00 | Portable X-Ray_26.pdf |

| Part_Num ber | Name | Asset_I D | Vendor | Cost_US D | Quantit y |
|-----------------|-----------------------------------|--------------|---------|--------------|--------------|
| 10128486 | QUENCH ELBOW ASSY-FLANGED | 5 | siemens | 435 | 4 |
| 10128499 | Aux. Vent blank(BD END) | 5 | siemens | 640 | 8 |
| 10128723 | Aux. Vent Blank(elbow end) | 5 | siemens | 270 | 15 |
| 10128733 | De-Mountable pin fitting kit | 5 | siemens | 890 | 1 |
| 10128734 | QV elbow fitting kit | 5 | siemens | 2700 | 1 |
| 10128742 | air and sea Freight assy | 5 | siemens | 750 | 5 |
| 10128924 | Li battery | 5 | siemens | 250 | 10 |
| 10128974 | de-coupler fitting kit | 5 | siemens | 375 | 1 |
| 10129376 | 4k filtered PRV adapter | 5 | siemens | 360 | 6 |
| 10129669 | OR98 pipe set kit | 5 | siemens | 500 | 3 |
| 10129671 | FCL pin kit | 5 | siemens | 2000 | 2 |
| 10129672 | quench valve | 5 | siemens | 1500 | 1 |
| 10144747 | Anti-Siphon Plate Adjustment Knob | 1 | Holmark | 50 | 6 |
| 10152525 | Servo Duo Guard filter | 11 | MAQUET | 100 | 8 |
| 31014789 | Aerogen Solo Nebulizer | 11 | MAQUET | 150 | 2 |
| 41014789 | HLS Module Advanced | 8 | MAQUET | 500 | 2 |
| 51014732 | Guide Rod Collar Clamp | 1 | Holmark | 15 | 7 |
| 58998123 | Li battary | 4 | philips | 140 | 9 |
| 61014859 | Bubble sensor | 8 | MAQUET | 200 | 3 |
| 110040031 | Couch Down position switch | 4 | PHILIPS | 550 | 3 |
| 110065761 | ROTOR BELT | 4 | PHILIPS | 100 | 6 |
| 110190131 | patient table limit swich cab | 4 | PHILIPS | 900 | 2 |
| 566016252 | external 4x CD ROM | 4 | PHILIPS | 765 | 15 |
| 566017651 | BRAKE SOLENOID | 4 | PHILIPS | 520 | 1 |
| 566019761 | fuse 150A/700V | 4 | PHILIPS | 30 | 11 |
| 566308451 | CLAMP ASSY | 4 | PHILIPS | 700 | 3 |
| 567474001 | portuguese | 4 | PHILIPS | 390 | 2 |

| SSN | Name | Phone_number | Company |
|------------|---------|--------------|----------------|
| 534890245 | Mahmoud | 318459362 | Soma Tech Intl |
| 546896213 | Ashraf | 1111647852 | MAQUET |
| 632598751 | Hany | 100025487 | Siemens |
| 1023589637 | Samy | 1125896472 | Philips |
| 1100235612 | Yasser | 211063542 | MAQUET |
| 1230470140 | Ayman | 147258369 | Samsung |
| 1283421801 | Khaled | 132990153 | Samsung |
| 1365987450 | Khaled | 1289751264 | zimmer Biomet |
| 1429932802 | Ehab | 321045128 | MAQUET |
| 1550221561 | Haitham | 182246042 | Zimmer Biomet |
| 1628129635 | Kareem | 291583547 | Soma Tech Intl |
| 1723091235 | Basem | 172532981 | AEgEA |
| 1723642532 | Mahmoud | 1215301432 | Soma Tech Intl |
| 1882044351 | Eslam | 182251618 | Siemens |
| 1902213572 | Eyad | 201872417 | AEgEA |
| 2019335814 | Yassin | 207135512 | Zimmer Biomet |
| 2047080647 | Mahmoud | 101234798 | Holmark |
| 2147483647 | Ahmed | 101234798 | Pilips |

| SSN | Order_number | Number_of_hours |
|------------|--------------|-----------------|
| 2147483647 | 1 | 7 |
| 1230470140 | 2 | 10 |
| 2147483647 | 2 | 10 |
| 1365987450 | 1 | 8 |
| 546896213 | 5 | 8 |
| 632598751 | 2 | 8 |
| 2047080647 | 5 | 5 |
| 546896213 | 1 | 4 |
| 632598751 | 2 | 9 |

| Order_number | Asset_ID | Name | Status | Creation_date | Repair/PM | Due_date | PM_date | PM_frequency | Priority | Description | Repair_cost |
|--------------|----------|----------------------|-------------|---------------|-----------|------------|------------|--------------|----------|--|-------------|
| 1 | 1 | Inspection, PM | Completed | 2020-04-15 | PM | 2020-05-01 | 2020-05-01 | Monthly | Low | Checked power, battery, alarms, tubes, cleaning and calibration | |
| 2 | 5 | Inspection, PM | Completed | 2019-06-05 | PM | 2019-07-02 | 2019-07-01 | Monthly | High | Inspecting and recording the MRI's cryogen levels. | |
| 3 | 4 | fix error | complete | 2020-03-31 | Repair | 2020-04-06 | 2020-05-17 | Yearly | High | fatal error | 700 |
| 4 | 4 | fix rotor error | In progress | 2020-05-04 | Repair | 2020-05-30 | 2020-05-17 | Yearly | Low | rotor error | 300 |
| 5 | 1 | fix | Not started | 2020-05-02 | Repair | 2020-05-14 | 2020-06-01 | Monthly | High | Guide Rod Collar Clamp of the syringe pump is broken, please fix. | |
| 6 | 3 | Inspection, PM | Not Started | 2020-05-08 | PM | 2020-05-20 | 2020-05-20 | Yearly | High | Checking electrodes, battery, synchronizer, connectors | |
| 7 | 6 | Inspection, PM | Not Started | 2020-04-03 | PM | 2020-04-10 | 2020-04-07 | Yearly | Low | Checking battery, probes, lamps and cleaning filters, transducers, keyboard | |
| 8 | 14 | Inspection, PM | Completed | 0000-00-00 | PM | 2019-03-18 | 2019-03-18 | Yearly | High | Checked battery, indicators, alarms, fuse, tubes, fluid levels | |
| 9 | 7 | Inspection, PM | Not Started | 2020-05-08 | PM | 2020-08-03 | 2020-08-03 | Yearly | Low | Checking battery, probes, lamps and cleaning filters, transducers, keyboard | |
| 10 | 6 | fix image artifacts | Completed | 2020-03-20 | Repair | 2019-04-10 | 2021-05-07 | Yearly | Low | Artifacts in the images, fixed by replacing transducer | |
| 11 | 3 | fix battery failure | completed | 2020-04-03 | Repair | 2020-04-15 | 2020-05-20 | Yearly | Low | Battery failure, fixed by replacing battery | 15000 |
| 12 | 5 | fix helium low level | completed | 2020-02-05 | Repair | 2020-02-22 | 2020-07-01 | Yearly | Low | Low helium level, fixed by helium filling | 50 |
| 13 | 11 | Inspection, PM | Completed | 2019-01-20 | PM | 2019-02-20 | 2019-02-19 | Monthly | High | Checked air filters, modes of ventilation, alarms, cleaning filters | |
| 14 | 11 | Inspection, PM | Completed | 2019-12-20 | PM | 2019-01-05 | 2019-02-19 | Monthly | High | Checked air filters, modes of ventilation, alarms, cleaning filters | |
| 15 | 1 | Inspection, PM | Completed | 2020-02-22 | PM | 2020-03-01 | 2020-03-01 | Monthly | Low | Check power, battery, alarms, tubes, cleaning and calibration | |
| 16 | 1 | Inspection, PM | Completed | 2020-03-20 | PM | 2020-04-01 | 2020-04-01 | Monthly | Low | Check power, battery, alarms, tubes, cleaning and calibration | |
| 17 | 15 | Inspection, PM | Completed | 2019-12-06 | PM | 2020-01-06 | 2020-01-06 | Monthly | High | Check connectors, electrodes, fuse, lubricate paper drive, replace battery | |
| 18 | 13 | Inspection, PM | Completed | 2020-03-20 | PM | 2020-04-11 | 2020-04-11 | Weekly | High | Checked and cleaned sensors, steam lines, replaced filter, verified temperature | |
| 19 | 12 | fix alarm failure | Not Started | 2020-05-20 | Repair | 2020-06-15 | 2019-09-08 | Yearly | Low | Alarm failure | |
| 20 | 10 | fix alarm | Completed | 2020-01-02 | PM | 2020-01-07 | 2020-01-21 | Monthly | High | Temperature sensor not working, fixed by replacing sensor | 100 |
| 21 | 10 | Inspection, PM | Completed | 2020-03-01 | PM | 2020-03-22 | 2020-03-21 | Monthly | High | Checked battery, mixer, alarms, connectors, calibration | |
| 22 | 10 | Inspection, PM | Completed | 2020-05-01 | PM | 2020-05-22 | 2020-05-21 | Monthly | High | Checked battery, mixer, alarms, connectors, lubricated motors | |
| 23 | 9 | Inspection, PM | Completed | 2018-09-01 | PM | 2018-10-02 | 2018-10-01 | Yearly | High | Checked motors, tubes, switches, alarms, pressure, replaced tube | |
| 24 | 9 | Inspection, PM | Completed | 2019-09-01 | PM | 2019-10-02 | 2019-10-01 | Yearly | High | Checked motors, tubes, switches, alarms, pressure, replaced battery | |
| 25 | 2 | Inspection, PM | Completed | 2019-09-30 | PM | 2019-10-08 | 2019-10-08 | Yearly | Low | Checked mattress, actuators, motors | |
| 26 | 2 | Inspection, PM | Completed | 2018-09-28 | PM | 2018-10-08 | 2018-10-08 | Yearly | Low | Checked mattress, actuators, motors | |
| 27 | 19 | Inspection, PM | Completed | 2018-09-20 | PM | 2018-10-02 | 2018-10-02 | Yearly | Low | Checked wires, battery, SpO2, alarms, cleaned connectors | |
| 28 | 19 | Inspection, PM | Completed | 2019-09-20 | PM | 2019-10-02 | 2019-10-02 | Yearly | Low | Checked wires, battery, SpO2, alarms, changed battery | |
| 29 | 19 | fix monitor problem | Not Started | 2020-05-05 | Repair | 2020-05-30 | 2020-10-02 | Yearly | Low | Monitor problem | |
| 30 | 17 | Inspection, PM | Completed | 2019-02-22 | PM | 2019-03-02 | 2019-03-02 | Yearly | Low | Checked wires, battery, SpO2, alarms, cleaned connectors, changed wire connector | |
| 31 | 17 | Inspection, PM | Completed | 2020-02-22 | PM | 2020-03-02 | 2020-03-02 | Yearly | Low | Checked wires, battery, SpO2, alarms | |
| 32 | 17 | Inspection, PM | Completed | 2021-02-22 | PM | 2021-03-02 | 2021-03-02 | Yearly | Low | Checked wires, battery, SpO2, alarms | |
| 33 | 23 | Inspection, PM | Completed | 2018-07-20 | PM | 2018-08-19 | 2018-08-19 | Monthly | High | Checked air filters, modes of ventilation, alarms, cleaned filters, tubes | |
| 34 | 23 | Inspection, PM | Completed | 2019-07-23 | PM | 2019-08-19 | 2019-08-19 | Monthly | High | Checked air filters, modes of ventilation, alarms, cleaned filters, tubes | |
| 35 | 20 | Inspection, PM | Completed | 2019-09-30 | PM | 2019-10-20 | 2019-10-20 | Yearly | Low | Checked mattress, actuators, motors, lubricated motors | |
| 36 | 21 | Inspection, PM | Completed | 2019-10-30 | PM | 2019-11-15 | 2019-11-15 | Yearly | Low | Checked mattress, actuators, motors, lubricated motors | |
| 37 | 22 | Inspection, PM | Completed | 2018-02-01 | PM | 2018-02-15 | 2018-02-15 | Yearly | Low | Checked mattress, actuators, motors | |
| 38 | 22 | Inspection, PM | Completed | 2019-02-01 | PM | 2019-02-15 | 2019-02-15 | Yearly | Low | Checked mattress, actuators, motors, lubricated motors | |
| 39 | 22 | Inspection, PM | Completed | 2020-02-04 | PM | 2020-02-15 | 2020-02-15 | Yearly | Low | Checked mattress, actuators, motors, lubricated motors | |

| Order_number | Part_used |
|--------------|------------|
| 4 | Li battary |
| 3 | ROTOR BELT |