Part 1 - Evaluation of Significance

Federal and Virginia historic rehabilitation tax credit programs

1. Owner of record: Ashby Mill Owner LLC, a Virginia limited liability company. The owner has full authority to make this application and to consent to the inspection of the property.

2. Property name and address: Ashby Mill, 410 Bridge Street, Danville, VA 24541. The property is located within the Danville Tobacco Warehouse and Residential District.

3. Request: certification that the building contributes to the significance of the registered historic district, for the purpose of the rehabilitation tax credit.

4. Contact: Riverside Heritage Development LLC, acting as authorized representative of the owner for all correspondence on this application.

NPS - APPROVED
March 14, 2023
Contributes to district

Description of physical appearance

1. The building is a five-story brick textile mill with a heavy-timber interior frame, segmental-arched window openings and a stepped parapet along Bridge Street.

2. The ground floor retains its original loading doors on the river elevation. Upper floors are open loft spaces divided by rows of timber columns at regular bays.

3. A stair tower and a later boiler house stand at the east end. The boiler house is a non-contributing addition and is excluded from this evaluation.

4. Date of construction: the mill was constructed in 1912 for the Ashby Cotton Manufacturing Company and operated as a spinning mill until 1958.

5. Alterations: several ground-floor openings were infilled in the 1960s. Roofing and most mechanical systems have been replaced over time.

Statement of significance

6. The mill is significant under Criterion A for its association with the textile industry that shaped the economy of Danville in the early twentieth century.

7. It is also significant under Criterion C as an intact example of slow-burn mill construction, with heavy timber framing, brick bearing walls and large daylight windows.

8. The building contributes to the district through its scale, materials and its relationship to the river and the adjacent warehouse blocks.

Integrity

9. The building retains integrity of location, setting, design, materials, workmanship, feeling and association. Infilled openings are reversible.

10. The historic window openings remain legible on all elevations, although a large share of the original sash has deteriorated.

11. Interior timber columns, beams and maple flooring survive on most floors.

Photographs and maps

12. Photographs 1 to 14 show the exterior elevations, the stair tower and representative interior spaces. A site plan and district map are attached.

13. Photograph key: north elevation (1 to 3), river elevation (4 to 6), east stair tower (7), interior floors 1 to 5 (8 to 14).

Owner certification

14. I certify that the information provided is, to the best of my knowledge, correct, and that I own the property described above.

Signed: Authorized Signatory, Ashby Mill Owner LLC

Date: February 2, 2023