## STRUCTURAL SAFETY & STABLITY CERTIFICATE

चार्मक सं- 78/जीय

Taolog - 09-02-2022

1. Certified that the building constructed at site, also satisfy the safety requirements as stipulated in the Indian Standards, Codes, Guildlines and the information given in the attached Building and understanding.

2. It is also certified that the structural design including safety from natural hazards

including earthquake has been done properly at site

Location/address of building:SITUATED AT NAI BASTI 194/1 SUMAN NAGAR, DHARMAPUR, DISTT.-DEHRADUN.

OWNER NAME: FOR SCHOOL NAMED GOVARDHA SARASWATI VIDYA MANDIR INTER COLLEGE THROUGH CHAIRMAN ANIL NANDA S/O NANAK CHAND.

Particulars of Building:-

A Ground coverage (SQMT.)

=503.04 SQ. MT.

B Total covered area (SQ.MT.)

=2374.43 SQ. MT.

C Maximum number of floors above the ground =G+3

Signature of owner

KAGHAV PARASHAR CA/18/99104


Signature of Architect

GEO. Damin. M

DOH-UK/G-1/ASE-11/2019

Signature of structural engineer

10 Work 5025



SIG. OF STR ENGG