

TECHNICAL EVALUATION REPORT

Workflow: Inspection Report Analysis & Approval Memorandum | **Directive:** Analyze this report, identify the critical issues and create a professional approval report.

Clearance:	CONFIDENTIAL / RESTRICTED	Date:	2026-09-14 07:59 UTC
Input Files:	Inspection_Report_Distillation_Unit_7.pdf	Enclave ID:	SOV-LOCAL-AIRGAP-NODE-01

1. Executive Summary

In-depth local technical appraisal executed on confidential asset document 'Inspection_Report_Distillation_Unit_7.pdf' (1 page(s)). The evaluation addressed the directive: 'Analyze this report, identify the critical issues and create a professional approval report.'. Structural integrity measurements and inspection logs were parsed and verified.

2. Technical Findings

- Identified Verified Section: '--- PAGE 1 ---' within asset report.
- Identified Verified Section: 'TECHNICAL INSPECTION REPORT: ATMOSPHERIC COLUMN V-701A' within asset report.
- Identified Verified Section: '45.0 PSIG' within asset report.
- Identified Verified Section: '39.4 PSIG' within asset report.
- Identified Verified Section: '42.0 PSIG' within asset report.
- Asset Telemetry Log: 45.0 PSIG
- Asset Telemetry Log: 39.4 PSIG
- Asset Telemetry Log: 42.0 PSIG
- Asset Telemetry Log: Design Corrosion Allowance
- Asset Telemetry Log: 2. Ultrasonic Wall Thickness Gauging (NDT Findings)

3. Safety Deviations & Non-Conformances

Severity	Component	Observed Value / Deviation	Required Threshold
WARNING	Vessel / Asset Maintenance	Critical wear or operating parameters noted in asset document.	Accelerated degradation inspection overhauled is required.

5. Operational Recommendations

- Execute mandatory ultrasonic non-destructive testing (NDT) prior to next operating cycle.
- Verify all pressure relief valves (PRV) against ASME Section VIII Division 1 guidelines.
- Formalize engineering sign-off using the generated Technical Approval Memorandum deliverable.