

EQUIPMENT INSPECTION FORM

Document ID

DOC-2026-0142

Equipment ID

EQ-1001

Inspection Date

2026-08-15

Location

Warehouse A

Equipment Type

Packaging Machine

Condition

Needs Review

Safety Check

☒ Passed

Repair Required

☒ Yes

Photo Attached

☐ No

Issue Description

Abnormal vibration detected

Next Inspection Date

2026-11-15

Inspector Role

Internal Technician