

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form		Effective 10-JUL-2026
		Location Houston (Corporate)	ETX ID 3.100.019.F01	
Printed by qchen@eagleanalytical.com from https://app.zenqms.com on 18-Sep-2026 at 2:11:40 PM UTC				
Page 1 of 6				

OOS Number: OOS-

Phase I

Section A – Test Details					
Initiator:		Test Date:		Date Initiated:	
Date of Incident:		Test Name:		Sample ID:	
Name of Analyst who Performed the Test:		Sample / Active Name		Lot #:	
		Dosage Form			
Description of Incident:			☐ Client Care notified of OOS ☐ Sterility and Endotoxin test related OOS; Client must be notified within 24 hours of OOS		
	SOP / Test Method #	Effective Date:	SOP / Test Method Rev:	Limits/Specification:	
Manager notified	Manager/designee name:	Date:	Quality Assurance Department notified:	Yes ☐ No ☐	
Section B – Investigation and Root Cause Analysis					
Personnel Discrepancy			Comments		
Analyst interviewed?	☐ Yes ☐ No ☐ N/A				
Correct samples analyzed?	☐ Yes ☐ No ☐ N/A				
Correct SOP / Test Method used/followed?	☐ Yes ☐ No ☐ N/A				
Correct sample collection/technique?	☐ Yes ☐ No ☐ N/A				
Are the Test Result Records Attached & Calculations Verified and Correct?	☐ Yes ☐ No ☐ N/A				
Is the analyst qualified to perform the test?	☐ Yes ☐ No ☐ N/A				
Is formula worksheet provided and verified?	☐ Yes ☐ No ☐ N/A				
Does the processing method/method set conform to the required specification?	☐ Yes ☐ No ☐ N/A				
Was the sample stored appropriately?	☐ Yes ☐ No ☐ N/A				
Material Discrepancy			Lot Number	Expiry Date	
Is the integrity of the sample(s) questionable?	☐ Yes ☐ No ☐ N/A				
Was the sample transported appropriately?	☐ Yes ☐ No ☐ N/A				
Are the other test results from this run under investigation?	☐ Yes ☐ No ☐ N/A				

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form	Effective 10-JUL-2026
Location Houston (Corporate)		ETX ID 3.100.019.F01	
Printed by qchen@eagleanalytical.com from https://app.zenqms.com on 18-Sep-2026 at 2:11:40 PM UTC			Page 2 of 6

OOS Number: OOS-

Appropriate/correct glassware used?	☐ Yes ☐ No ☐ N/A		
Are reagents stored in proper condition and not expired?	☐ Yes ☐ No ☐ N/A		
Standard Used			
Solvent Used			
Is the standard the source of the root cause?	☐ Yes ☐ No ☐ N/A		
Has the analyst been instructed to keep the original test solution for possible retesting?	☐ Yes ☐ No ☐ N/A		
Equipment Discrepancy		Equipment ID	Calibration Due Date
Was the instrument set up correctly?	☐ Yes ☐ No ☐ N/A		
Is the clean room facility certified?	☐ Yes ☐ No ☐ N/A		
System Performance Check (if applicable)?	☐ Yes ☐ No ☐ N/A		
System Suitability RSD < 2% (PDA)?	☐ Yes ☐ No ☐ N/A		
System Suitability RSD < 10% (QDA, CAD)?	☐ Yes ☐ No ☐ N/A		
Do the environmental monitoring results conform to required standards?	☐ Yes ☐ No ☐ N/A		
Do the controls (i.e., positive, negative, etc.) conform to the required standards?	☐ Yes ☐ No ☐ N/A		
Is equipment/instrument functional and calibrated/qualified/certified/PM?	☐ Yes ☐ No ☐ N/A		

	CORP-FORM-21 v11.1	Category: Form Corporate Name: Laboratory OOS Investigation Form	Effective 10-JUL-2026
Location Houston (Corporate)		ETX ID 3.100.019.F01	
Printed by qchen@eagleanalytical.com from https://app.zenqms.com on 18-Sep-2026 at 2:11:40 PM UTC			Page 3 of 6

OOS Number: OOS- 262080

Are chromatogram/spectra/raw data correct?				☐ Yes ☐ No ☒ N/A	Not Applicable	Not Applicable
Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)						
☒ N/A ☐ Re-injection of sample vial ☐ Re-injection of original standard vial ☐ Re-vialing of original working standard solution		☐ Re-vialing of original working sample solution ☐ Re-dilution of a working sample solution from the original stock ☐ Re-dilution of a working standard solution from the original stock standard ☐ Other: <u>N/A QYC 08Sep2026</u>				
Section D – Phase I Summary						
Phase I Summary: All analysts involved in the preparation, processing, aliquoting, and reading of the samples, Andrew Carrillo, Gabrielle Surber, America Alanis, and Cuong Du, were interviewed comprehensively. Their responses are documented throughout this report. This investigation was performed as per MICRO-SOP-53 Sterility Test Out-of-Specification (OOS) Investigation Procedure. Upon arrival, the sample was stored refrigerated in accordance with the client instructions. Both sample prepping analyst Andrew Carrillo and processing analyst Gabrielle Surber inspected the sample during preparation and processing. No leaks or visible turbidity were observed, and no evidence of compromised container integrity was identified. All reagents and supplies mentioned in the material section above were stored according to supplier recommendations, and their integrity was visually verified before utilization. Moreover, all reagents and supplies had valid expiration dates. The functionality of all equipment was confirmed by reviewing data generated by our comprehensive in-house continuous monitoring system. The cleanroom suite used for processing procedures (CR114) comprises three interconnected sections: the innermost ISO 7 cleanroom (114B), which connects to the middle ISO 7 buffer room (114A), and then to the outermost ISO 8 anteroom (114). A positive air pressure system is maintained throughout the suite to ensure controlled, unidirectional airflow from 114B through 114A and into 114. The innermost ISO 7 cleanroom 114B and its ISO 5 BSC E001316 were thoroughly cleaned and prepared before initiating testing by analyst Gabrielle Surber as per MICRO-SOP-2 (Environmental Monitoring of the Clean Room Facility) and MICRO-SOP-9 (Cleaning and Disinfecting Procedure for Microbiology). For Celsis aliquoting, intermediate ISO 7 buffer room 114A and its ISO 5 BSC E001798 were thoroughly cleaned and prepared by analyst Cuong Du before initiating testing as per MICRO-SOP-44 and MICRO-SOP-9. Both BSCs,						

OOS Number: OOS-

Phase I Summary (continued):

OOS Number: OOS-

Phase I Summary (continued):

