



QUALITY SYSTEM

FORM

DOCUMENT #: 3.100.019.F01

LEVEL: 3

Effective Date:

APPROVED

JEsqueda , 9/30/2025, 4:15:53 PM

Revision #: 11

TITLE:

LABORATORY OOS INVESTIGATION FORM

Page 1 of 6

OOS Number: OOS- 261186

Phase I

Section A – Test Details

Initiator:	Simin Mohammad (written by Maryam Naeem)	Test Date:	07-May-2026	Date Initiated:	18-May-2026
Date of Incident:	18-May-2026	Test Name:	Environmental Monitoring	Sample ID:	ETX-260518-0254
Name of Analyst who Performed the Test:	Simin Mohammad (Weekly Active Air Sampling Plate Setup)	Sample / Active Name	EM SMO 116A Air 07MAY2026	Lot #:	EM SMO 116A Air 07MAY2026
	Samera A. Salim (Weekly Active Air Sampling Plate Readers)	Dosage Form	Plate		
Description of Incident:	The CFU count for the environmental monitoring plate exceeded the action level.		☐ Client Care notified of OOS ☐ Sterility and Endotoxin test related OOS; Client must be notified within 24 hours of OOS		
	SOP / Test Method # 2.600.002	Effective Date: 05 Aug 2025	SOP / Test Method Rev: 15	Limits/Specification: Alert Level: >= 8 CFU/Plate Action Level: > 10 CFU/Plate	
Manager notified	Manager/designee name: Kathan Parikh	Date: 18-May-2026	Quality Assurance Department notified:	Yes ☐ No ☐	

Section B – Investigation and Root Cause Analysis

Personnel Discrepancy		Comments
Analyst interviewed?	☒ Yes ☐ No ☐ N/A	Yes, analysts Simin Mohammad and Samera A. Salim were interviewed comprehensively.
Correct samples analyzed?	☐ Yes ☐ No ☒ N/A	N/A
Correct SOP / Test Method used/followed?	☒ Yes ☐ No ☐ N/A	Yes, as per SOP 2.600.002
Correct sample collection/technique?	☒ Yes ☐ No ☐ N/A	Yes, as per SOP 2.600.002
Are the Test Result Records Attached & Calculations Verified and Correct?	☒ Yes ☐ No ☐ N/A	Yes, Information is available in EagleTrax under ETX-260518-0254.
Is the analyst qualified to perform the test?	☒ Yes ☐ No ☐ N/A	Yes, the analysts are trained and qualified by quality to perform the test.
Is formula worksheet provided and verified?	☐ Yes ☐ No ☒ N/A	Not Applicable
Does the processing method/method set conform to the required specification?	☐ Yes ☐ No ☒ N/A	Not Applicable
Was the sample stored appropriately?	☒ Yes ☐ No ☐ N/A	Yes, as per SOP 2.600.002
Material Discrepancy		Lot Number
Is the integrity of the sample(s) questionable?	☐ Yes ☐ No ☒ N/A	
Was the sample transported appropriately?	☐ Yes ☐ No ☒ N/A	
Are the other test results from this run under investigation?	☐ Yes ☐ No ☒ N/A	



QUALITY SYSTEM

FORM

DOCUMENT #: 3.100.019.F01

LEVEL: 3

Effective Date:

APPROVED
JEsqueda, 9/30/2025, 4:15:53 PM

Revision #: 11

TITLE:

LABORATORY OOS INVESTIGATION FORM

Page 2 of 6

OOS Number: OOS- 261186

Appropriate/correct glassware used?	☐ Yes ☐ No ☒ N/A		
Are reagents stored in proper condition and not expired?	☒ Yes ☐ No ☐ N/A	TSA Plate: 1011543730	TSA Plate: 29SEP2026
Standard Used	Not Applicable	Not Applicable	Not Applicable
Solvent Used	Not Applicable	Not Applicable	Not Applicable
Is the standard the source of the root cause?	☐ Yes ☐ No ☒ N/A		
Has the analyst been instructed to keep the original test solution for possible retesting?	☐ Yes ☐ No ☒ N/A		
Equipment Discrepancy		Equipment ID	Calibration Due Date
Was the instrument set up correctly?	☒ Yes ☐ No ☐ N/A	Please see below	Please see below
Is the clean room facility certified?	☒ Yes ☐ No ☐ N/A	CR116 (E001738)	December 2026
System Performance Check (if applicable)?	☐ Yes ☐ No ☒ N/A	N/A	N/A
System Suitability RSD < 2% (PDA)?	☐ Yes ☐ No ☒ N/A	Not Applicable	Not Applicable
System Suitability RSD < 10% (QDA, CAD)?	☐ Yes ☐ No ☒ N/A	Not Applicable	Not Applicable
Do the environmental monitoring results conform to required standards?	☐ Yes ☐ No ☒ N/A	Not Applicable	Not Applicable
Do the controls (i.e., positive, negative, etc.) conform to the required standards?	☐ Yes ☐ No ☒ N/A	Not Applicable	Not Applicable
Is equipment/instrument functional and calibrated/qualified/certified/PM?	☒ Yes ☐ No ☐ N/A	Incubator E001034 (Sensor E001501) Incubator E001031 (Sensor E001505)	Aug 2026 Feb 2027 Aug 2026 Feb 2027



QUALITY SYSTEM

FORM

DOCUMENT #: 3.100.019.F01

LEVEL: 3

Effective Date:

APPROVED

JEsqueda , 9/30/2025, 4:15:53 PM

Revision #: 11

TITLE:

LABORATORY OOS INVESTIGATION FORM

Page 3 of 6

OOS Number: OOS- 261186

Are chromatogram/spectra/raw data correct?

☐ Yes☐ No☒ N/A

Not Applicable

Not Applicable

Section C – Evaluation of Laboratory Testing/Hypothesis Testing (if applicable)

☒ N/A☐ Re-injection of sample vial☐ Re-injection of original standard vial☐ Re-vialing of original working standard solution☐ Re-vialing of original working sample solution☐ Re-dilution of a working sample solution from the original stock☐ Re-dilution of a working standard solution from the original stock standard☐ Other: N/A QYC

Section D – Phase I Summary

Phase I Summary:

The analysts involved in the Weekly Active Air Sampling plate setup, Simin Mohammad, and the analysts involved in reading the plate, Samera A. Salim, were interviewed comprehensively. Their answers are recorded throughout this document. The EM plates were stored in compliance with the supplier's recommendations, and their integrity was visually inspected prior to use. Furthermore, the plates were confirmed to be within their valid expiration dates. All the supplies were thoroughly disinfected according to SOP 2.600.018. The functionality of both incubators was verified through a review of data obtained from our comprehensive in-house continuous monitoring system. Weekly Active Air Sampling was performed by analyst Simin Mohammad during weekly environmental monitoring, in Cleanroom Suite 116A, on 07 May 2026 as per SOP 2.600.002 - Environmental Monitoring of the Cleanroom Facility. The plates were initially incubated at a temperature of 30 – 35°C in incubator E001031 for a minimum duration of 48 hours, commencing on 07 May 2026. Following completion of minimum of 48 hours of incubation on 11 May 2026, the plates were further incubated for minimum of 5 days, with the incubation concluding on 18 May 2026. Please see Table 1 for detailed information on the observations during respective incubations. Based on the observations in Table 1, since the CFU count exceeded the action level for the Weekly Active Air Sampling plate, the plate was submitted for Microbial Identification under ETX-260518-0254. The colony was identified as *Kocuria palustris* (Gram (+) cocci). To observe if the organisms identified were transient in nature or recurring, environmental monitoring plates for the analyst Simin Mohammad and Cleanroom Suite 116A were bracketed to include date before testing and date after testing as detailed in Table 2 (please see attached).

	QUALITY SYSTEM		FORM
	DOCUMENT #: 3.100.019.F01		LEVEL: 3
	Effective Date:	APPROVED JEsqueda , 9/30/2025, 4:15:53 PM	Revision #: 11
TITLE:	LABORATORY OOS INVESTIGATION FORM		Page 4 of 6

OOS Number: OOS- 261186

Phase I Summary (continued):

Environmental Monitoring Summary: Weekly surface and active air sampling for CR116 for the previous week and following week of testing showed no microbial growth. However, the Weekly Active Air Sampling for CR116 for the week of testing, performed on 07 May 2026 by analyst SMO, exhibited 748 CFUs on EM SMO 116A Air 07MAY2026, which were identified as *Kocuria palustris* (Gram (+) cocci). Routine monitoring on the date of testing showed no growth across other monitored locations. During the interview with the analyst, they indicated that no obvious abnormalities or deviations in the testing procedure were observed. All the samples were thoroughly disinfected prior to testing. Moreover, the cleanroom suites in CR116 were thoroughly cleaned and prepared before initiating testing as per SOP 2.600.002 and SOP 2.600.018. Monthly cleaning and disinfection of the cleanroom facility and containing Biosafety Cabinets were performed on 30 Apr 2026 as per SOP 2.600.018 by analyst Rey Estrada. It was documented that all H2O2 indicators passed. Additionally, cleaning and disinfecting was performed both prior to and after the testing process as per SOP 2.600.018. It is important to note that no samples processed within that week in CR116 failed Sterility component testing that week.

**QUALITY SYSTEM****FORM****DOCUMENT #: 3.100.019.F01****LEVEL: 3**

Effective Date:

APPROVED

JEsqueda , 9/30/2025, 4:15:53 PM

Revision #: 11

TITLE:**LABORATORY OOS INVESTIGATION FORM****Page 5 of 6****OOS Number: OOS-** 261186**Phase I Summary (continued):**

Based on the findings outlined in the preceding sections, the Out-Of-Specification (OOS) result observed for the weekly Environmental Monitoring (EM) Weekly Active Air Sampling plate may be attributed to a potential laboratory or sampling error. It is important to note that the product samples are processed exclusively within the ISO 5 Primary Engineering Control (BSC) and are not exposed to the background environment in the ISO 8 or ISO 7 areas. Furthermore, all sample containers and supplies are thoroughly disinfected during transfer across the ISO 8 to ISO 7 to ISO 5 cascade. Additionally, no sample tested during that week in CR116 failed Sterility testing, confirming that the elevated environmental reading had no impact on sample integrity. Therefore, no preventive and corrective actions are deemed necessary at this time.



QUALITY SYSTEM

FORM

DOCUMENT #: 3.100.019.F01

LEVEL: 3

Effective Date:

APPROVED

JEsqueda , 9/30/2025, 4:15:53 PM

Revision #: 11

TITLE:

LABORATORY OOS INVESTIGATION FORM

Page 6 of 6

OOS Number: OOS- 261186

Has root cause been identified as a possible laboratory error?

Note: Root cause must be conclusive, verifiable, and well-documented.☒ Yes☐ If retesting is **required**, complete Phase II of the OOS (initiate Form 3.100.019.F02).☐ No, the OOS result is valid.

Reviewer comment(s):

Transient contamination. No impact to product quality.

Prepared by (Print):

Maryam Naeem

Signature/Date:

Lab Manager/Designee (Print):

Kathan Parikh

Signature/Date:

Section E – Quality Disposition

Can investigation be closed?

☐ Yes☐ Original result is valid.☐ No, initiate Form 3.100.019.F02.

Approved by QA Representative (Print):

Signature/Date:

Table 1: Read Dates & Incubation Observation

ETX Submission ID	Set-up Analyst & Date	Sampling Site & Location	Plate Reading Analyst (≥ 48H)	CFUs Observed after 48 Hour Incubation at 30–35°C (E001031)	Plate Reading Analyst (NLT 5 days)	CFUs Observed after NLT 5-day Incubation at 20–25°C (E001034)	Microbial Identification
ETX-260518-0254	SMO 07-May-2026	Weekly Active Air Sampling Plate (Cleanroom Suite 116 (ISO 7 116A))	SMO	748 CFU on EM SMO 116A Air 07MAY2026	SMO	748 CFU on EM SMO 116A Air 07MAY2026	Kocuria palustris (Gram (+) cocci)

Table 2: Environmental Monitoring for Analyst & Cleanroom

Environmental Monitoring (EM) Sampling Site	Frequency	Date (DDMMYYYY)	Analyst (Initials)	Day /Week(s)	Observation	Plate ETX ID	Microbial ID	Notes
Personnel EM Bracketing								
Personal (Left & Right Touch)	Daily	06 May 2026	SMO	Date Before Testing	No growth	N/A	N/A	None
Personal (Left & Right Touch)	Daily	07-May-2026	SMO	Date of Testing	No growth	N/A	N/A	None
Personal (Left & Right Touch)	Daily	08 May 2026	SMO	Date After Testing	No growth	N/A	N/A	None
Biological Safety Cabinet (BSC) EM Bracketing								
Surface Sampling of ISO 5 (4 loc)	Daily	06 May 2026	SMO	Date Before Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 loc)	Daily	07-May-2026	SMO	Date of Testing	No growth	N/A	N/A	None
Surface Sampling of ISO 5 (4 loc)	Daily	08 May 2026	SMO	Date After Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 loc)	Daily	06 May 2026	SMO	Date Before Testing	No growth	N/A	N/A	None
Settling Sampling of ISO 5 (2 loc)	Daily	07-May-2026	SMO	Date of Testing	No growth	ETX-260518-0254	Kocuria palustris (Gram (+) cocci)	None
Settling Sampling of ISO 5 (2 loc)	Daily	08 May 2026	SMO	Date After Testing	No growth	N/A	N/A	None
Weekly Active Air Sampling Bracketing								
Active Air Sampling of Cleanrooms	Weekly	07 May 2026	SMO	Week (On or After Date)	No growth	N/A	N/A	None
Surface Sampling of Anteroom & Cleanroom Bracketing								
Surface Sampling of Cleanrooms	Weekly	07 May 2026	SMO	Week (On or After Date)	No growth	N/A	N/A	None