

# Final Inspection Report



Field	Value
Inspection Date	2025-10-23
Supplier Name	kkk
Item Description	12
Design No	12
Colour	222
Inspector Name	11
Fabric Quality	
Merchandiser Name	
Order Quantity	
Presented Quantity	
No. of Pieces Inspected	
Delivery Date	
Total Cartons	
Inspected Cartons	
Product Category	Women
Sampling Range	151–280
Inspection Result	<b>REWORK</b>



Defect Category	Accept Limit	Reject Limit	Actual
Minor Defects	2	3	<b>0</b>
Major Defects	1	2	<b>0</b>



## Final Comments:



N/A

# Inline Pictures

















# PP Sample Pictures









**Signatures**

**QC Signature:**



**SUPPLIER Signature:**



**AQM Signature:**



**MERCH Signature:**

