

AUTOMATED QUALITY INSPECTION REPORT

Inspection ID: TEST-INS-4c0728 | Date: 2026-08-09T10:05:00

Parameter	Inspection Value
Product Type	Gear
Inspection Status	PASS
Defect Category	None
Confidence Score	98.0%
Processing Latency	30.0 ms
Width (mm)	50.00 mm
Height (mm)	50.00 mm
Area (mm²)	1963.50 mm²

15-Stage OpenCV Computer Vision Pipeline Diagnostic Log

#	Stage Name	Latency	Status	Technical Diagnostic
1	Read Image	2.0 ms	PASS	OK