PROPERTY INSPECTION REPORT

Inspection date: August 4, 2026
Property address: 1420 Oak Street, Mesa Verde, CA
SYNTHETIC SAMPLE DOCUMENT.

STRUCTURE

Foundation: concrete slab on grade.
Exterior walls: reinforced concrete masonry units (CMU).
No significant cracking observed at accessible areas.

ELECTRICAL

This section is provided for the intended user and intended use stated in the engagement letter.
The analysis relies on information furnished by the owner and on public sources believed to be reliable.
No responsibility is assumed for matters that are legal in nature or for hidden conditions.
Comparable data were confirmed with a party to each transaction where possible.
Photographs and maps are included in the addenda for reference only.
This section is provided for the intended user and intended use stated in the engagement letter.

PLUMBING

This section is provided for the intended user and intended use stated in the engagement letter.
The analysis relies on information furnished by the owner and on public sources believed to be reliable.
No responsibility is assumed for matters that are legal in nature or for hidden conditions.
Comparable data were confirmed with a party to each transaction where possible.
Photographs and maps are included in the addenda for reference only.
This section is provided for the intended user and intended use stated in the engagement letter.

ROOF

Covering: composition shingle; moderate granule loss observed.
Replacement date could not be determined from available records.
The owner did not provide permit history.

FIRE PROTECTION

Fire sprinklers: none observed. Smoke alarms present in units.