






A Asset Details										
Asset Group :		Mechanical			Model :					
Asset Category :		Building Machinery			Capacity :					
Asset Type :		Passenger / Service Lift			Location Code :		HQA00G			
Task No :		M004A			PM Start Date/Time :		15/7/2019 16:34:34			
Work Order No :		PBNMHQ19070800002			PM End Date/Time :		15/7/2019 17:21:53			
B Safety Precaution / General Guidelines prior to maintenance activity										
The following guidelines shall be followed: 1. To switch off/lock main isolator or MCCB. 2. To check no power supply at control panels. 3. To use proper signage on electrical panels. 4. To use proper safety attire when working on high levels.										
C Qualitative Tasks										
	Description				Freq	Pass	Fail	N/A	Remark	
1	To check lift intercom system functionality				W	X			lulus lagi. dah check.	
2	To check bell system functionality				W	X			lulus	
3	To check ventilation fan system functionality				W	X			lulus	
4	To check lighting system functionality				W	X			lulus	
5	To test lift operation and travelling condition				W		X		gagal	
6	To check car lift button functionality				W	X			lulus	
7	To check car lift cleanliness condition				W		X		gagal	
8	To check operation panel box lock condition (COP)				W	X			lulus	
9	To check lift hall button and car lift PI indicator functionality				W	X			lulus lagi	
D Quantitative Tasks										
	Description	Units	Set Value	Measured Values	Limit / Tolerance	Freq	Pass	Fail	N/A	Action
E Spare Parts / Material Used (if any)										
1. item 1 2. item 2										
F Additional Report										
Yes			No		Refer to					
G Comments / Remarks										
so far so good										
Service By			Checked By			Verified By				
 Name : Technician2 Date : 15/7/2019 17:21:53			 Name : Facility Supervisor Date : 15/7/2019 17:22:56			 Name : Engineer Date : 15/7/2019 17:24:45				

Maintenance Image : Before



Description : image before
Time Taken : 15/7/2019 16:34:51 16:34:51
Longitude : 101.676666
Latitude : 2.986711

Maintenance Image : During



Description : image during satu
Time Taken : 15/7/2019 16:42:58 16:42:58
Longitude : 101.676662
Latitude : 2.986702



Description : image during dua
Time Taken : 15/7/2019 16:45:02 16:45:02
Longitude : 101.676672
Latitude : 2.986703



Description : image during tiga
Time Taken : 15/7/2019 16:45:16 16:45:16
Longitude : 101.676670
Latitude : 2.986710

Maintenance Image : After



Description : image after
Time Taken : 15/7/2019 16:44:46 16:44:46
Longitude : 101.676655
Latitude : 2.986708