




A Asset Details										
Asset Group :		Mechanical			Model :					
Asset Category :		Building Machinery			Capacity :					
Asset Type :		Passenger / Service Lift			Location Code :		HQA00G			
Task No :		M004A			PM Start Date/Time :		15/7/2019 17:05:20			
Work Order No :		PBNMHQ19070100001			PM End Date/Time :		15/7/2019 17:14:35			
B Safety Precaution / General Guidelines prior to maintenance activity										
The following guidelines shall be followed: 1. To switch off/lock main isolator or MCCB. 2. To check no power supply at control panels. 3. To use proper signage on electrical panels. 4. To use proper safety attire when working on high levels.										
C Qualitative Tasks										
	Description					Freq	Pass	Fail	N/A	Remark
1	To check lift intercom system functionality					W	X			lift ok
2	To check bell system functionality					W	X			bell ok
3	To check ventilation fan system functionality					W	X			fan ok
4	To check lighting system functionality					W	X			lighting ok
5	To test lift operation and travelling condition					W	X			travelling on good
6	To check car lift button functionality					W	X			lift button all ok
7	To check car lift cleanliness condition					W	X			got vomit stain but ok. not smelly
8	To check operation panel box lock condition (COP)					W	X			
9	To check lift hall button and car lift PI indicator functionality					W	X			
D Quantitative Tasks										
	Description	Units	Set Value	Measured Values	Limit / Tolerance	Freq	Pass	Fail	N/A	Action
E Spare Parts / Material Used (if any)										
F Additional Report										
Yes		No		Refer to						
G Comments / Remarks										
So far all functions well. just a bit vomit stain in lift. need custo to clean up										
Service By			Checked By			Verified By				
 Name : Technician 1 Date : 15/7/2019 17:14:35			 Name : Facility Supervisor Date : 20/7/2019 21:50:07			 Name : Date :				

Maintenance Image : Before




Description :

Time Taken : 15/7/2019 17:10:09 17:10:09

Longitude : 101.731135

Latitude : 3.224427

Maintenance Image : During



Description :

Time Taken : 15/7/2019 17:10:49 17:10:49

Longitude : 101.731220

Latitude : 3.225966



Description :

Time Taken : 15/7/2019 17:11:57 17:11:57

Longitude : 101.731238

Latitude : 3.225932



Description :

Time Taken : 15/7/2019 17:12:23 17:12:23

Longitude : 101.731233

Latitude : 3.225923

Maintenance Image : After



Description :

Time Taken : 15/7/2019 17:11:25 17:11:25

Longitude : 101.731240

Latitude : 3.225922