






A Asset Details										
Asset Group :		Mechanical				Model :				
Asset Category :		Building Machinery				Capacity :				
Asset Type :		Passenger / Service Lift				Location Code :		HQA00G		
Task No :		M004A				PM Start Date/Time :		15/7/2019 16:34:34		
Work Order No :		PBNMHQ19070800002				PM End Date/Time :		15/7/2019 17:21:53		
B Safety Precaution / General Guidelines prior to maintenance activity										
The following guidelines shall be followed: 1. To switch off/lock main isolator or MCCB. 2. To check no power supply at control panels. 3. To use proper signage on electrical panels. 4. To use proper safety attire when working on high levels.										
C Qualitative Tasks										
	Description					Freq	Pass	Fail	N/A	Remark
1	To check lift intercom system functionality					W	X			lulus lagi. dah check.
2	To check bell system functionality					W	X			lulus
3	To check ventilation fan system functionality					W	X			lulus
4	To check lighting system functionality					W	X			lulus
5	To test lift operation and travelling condition					W		X		gagal
6	To check car lift button functionality					W	X			lulus
7	To check car lift cleanliness condition					W		X		gagal
8	To check operation panel box lock condition (COP)					W	X			lulus
9	To check lift hall button and car lift PI indicator functionality					W	X			lulus lagi
D Quantitative Tasks										
	Description	Units	Set Value	Measured Values	Limit / Tolerance	Freq	Pass	Fail	N/A	Action
E Spare Parts / Material Used (if any)										
1. item 1 2. item 2										
F Additional Report										
Yes No					Refer to					
G Comments / Remarks										
so far so good										
Service By  Name : Technician2 Date : 15/7/2019 17:21:53				Checked By  Name : Facility Supervisor Date : 15/7/2019 17:22:56				Verified By  Name : Engineer Date : 15/7/2019 17:24:45		

Maintenance Image : Before



Description : image before
Time Taken : 15/7/2019 16:34:51 16:34:51
Longitude : 101.676666
Latitude : 2.986711

Maintenance Image : During



Description : image during satu
Time Taken : 15/7/2019 16:42:58 16:42:58
Longitude : 101.676662
Latitude : 2.986702



Description : image during dua
Time Taken : 15/7/2019 16:45:02 16:45:02
Longitude : 101.676672
Latitude : 2.986703



Description : image during tiga
Time Taken : 15/7/2019 16:45:16 16:45:16
Longitude : 101.676670
Latitude : 2.986710

Maintenance Image : After



Description : image after
Time Taken : 15/7/2019 16:44:46 16:44:46
Longitude : 101.676655
Latitude : 2.986708