





A Asset Details										
Asset Group :		Mechanical			Model :					
Asset Category :		Building Machinery			Capacity :					
Asset Type :		Passenger / Service Lift			Location Code :		HQA00G			
Task No :		M004A			PM Start Date/Time :		18/7/2019 19:50:10			
Work Order No :		PBNMHQ19072900005			PM End Date/Time :		18/7/2019 20:48:24			
B Safety Precaution / General Guidelines prior to maintenance activity										
The following guidelines shall be followed: 1. To switch off/lock main isolator or MCCB. 2. To check no power supply at control panels. 3. To use proper signage on electrical panels. 4. To use proper safety attire when working on high levels.										
C Qualitative Tasks										
	Description					Freq	Pass	Fail	N/A	Remark
1	To check lift intercom system functionality					W	X			
2	To check bell system functionality					W	X			
3	To check ventilation fan system functionality					W	X			works fine
4	To check lighting system functionality					W	X			
5	To test lift operation and travelling condition					W	X			
6	To check car lift button functionality					W	X			
7	To check car lift cleanliness condition					W	X			
8	To check operation panel box lock condition (COP)					W	X			
9	To check lift hall button and car lift PI indicator functionality					W	X			
D Quantitative Tasks										
	Description	Units	Set Value	Measured Values	Limit / Tolerance	Freq	Pass	Fail	N/A	Action
E Spare Parts / Material Used (if any)										
1. mat1 2. mat2										
F Additional Report										
Yes		No		Refer to						
G Comments / Remarks										
all cunsss										
Service By			Checked By			Verified By				
										
Name : Technician 1			Name : Facility Supervisor			Name : Engineer				
Date : 18/7/2019 20:48:24			Date : 18/7/2019 20:50:12			Date : 18/7/2019 20:51:32				

Maintenance Image : Before



Description : Test1
Time Taken : 18/7/2019 19:57:50 19:57:50
Longitude : 101.722564
Latitude : 3.133996

Maintenance Image : During



Description : Test2
Time Taken : 18/7/2019 20:00:06 20:00:06
Longitude : 101.722734
Latitude : 3.133620

Maintenance Image : After



Description :
Time Taken : 18/7/2019 20:02:55 20:02:55
Longitude : 101.722424
Latitude : 3.133729