

WELLDONE MOTORS

AUTHORISED REPAIR & BODY SHOP
Kodigehalli Main Road, Bengaluru
Ph : 098864 01459

Estimate Type	Accident Repair
Estimate Date	25/06/2026
Accident Date	25/06/2026
Service Advisor	—
Payment Type	Insurance Claim

Owner Details		Vehicle & Policy Details	
Name	Shamsudheen KH	Odometer Reading	57,981 km
Vehicle No.	KL02 BB 7659	Policy No.	1007003126P102830663
RC No.	KLRC A0818777	Accident Date	25/06/2026

S.No.	Description	Amount (₹)
1	Headlight Assembly (2 Pieces)	89,120.00
2	Bumper Assembly	45,000.00
3	Fog Light Assembly Kit	14,156.00
4	Bonnet Repair (Including Painting)	8,000.00
5	Labour Charges	35,000.00
Total Estimate		₹ 1,91,276.00

Total Estimate Value (in words): <i>Rupees One Lakh Ninety One Thousand Two Hundred Seventy Six Only</i>

Remarks:

Vehicle received with front-end accident damage.
Estimate prepared for insurance claim assessment purposes.
Parts to be replaced / repaired as per customer approval.

for WELLDONE MOTORS

Note: This is a preliminary estimate. Final billed amount may vary based on actual parts and labour required.

Authorised Signatory