



Proval Industrial Co., Ltd.

No.11. Youth 9th Rd, Youth Industry Park, Dajia, Taichung Hsien, Taiwan R.O.C

TEL:+886-4-26816566-8 FAX:+886-4-26815279

E-mail:proval@ms17.hinet.net http://www.proval.com.tw

Inspection Certificate (EN 10204-3.1)	ISO 9001:2015 Certificate No.: 1210041694 TMS
Customer:GM	Order-No:PO86953 Certificate-No:26041001

Specification	☐ PED (97/23/EC), Annex 1, section 4 and section 7.5	☒ S.E.P
Material	1.4308 EN 10213 2007	
Melting process,	(E):electric furnace	
Heat Treatment	☐ 1080°C / 1h, AT QW / solution annealing and quenched by water	
Marking	☒ Grade of Material ☒ Nominal Pressure ☐ Year	☒ Nominal Size ☒ Heat Number ☐ Type No. CE0036
Melter Mark	☐ ARBON	

Extend of material delivery

Item No.	Article	DN (Size)	PN (Class)	Quantity (PCS)	Heat No. Specimen No
60129609	M216-86953-15/20/25/30	50	16	104	yJHD、qWOD、qWCD、IXDD、 yHLD、yHMD

Leak and pressure test according to ☒ EN 12266-1 ☐ ANSI B16.34-API598 ☐ MSS SP-134

Article.	DN (Size)	PN (Class)	Temperature	Shell strength testing			Closure testing			Result
				Test Pressure	Test medium	Duration	Test Pressur	Test medium	Durati on	
M216	50	16	RT	23bar	Water	15sec	6bar	Air	15sec	ok

Result The requirements are fulfilled, as listed in Annex 1.

Place:ZhongShan G.D

Date:Apr.10.2026

Works inspector: XTB



Proval Industrial Co., Ltd.

No.11. Youth 9th Rd, Youth Industry Park, Dajia, Taichung Hsien, Taiwan R.O.C

TEL:+886-4-26816566-8 FAX:+886-4-26815279

E-mail:proval@ms17.hinet.net http://www.proval.com.tw

Inspection Certificate (EN 10204-3.1)	ISO 9001:2015 Certificate No.: 1210041694 TMS
Customer:GM	Order-No:PO86953 Certificate-No:26041001

Annex 1 : Test Results

A) Chemical analysis

Heat No.	C %	Si %	Mn %	P %	S %	Ni %	Cr %	Cu %			
DIN EN 10213-16 1.4308	≤0.07	≤1.50	≤1.5	≤0.040	≤0.030	8.00 11.00	18.00 20.00	≤0.5			
yJHD	0.046	0.800	1.230	0.036	0.0040	18.280	18.28	0.084			
qWOD	0.050	0.740	1.100	0.032	0.0040	8.290	18.38	0.066			
qWCD	0.050	0.830	0.980	0.024	0.0030	8.440	18.38	0.128			
IXDD	0.045	0.610	1.150	0.037	0.0060	8.240	18.20	0.068			
yHLD	0.047	0.810	1.100	0.036	0.0040	8.240	18.17	0.115			
yHMD	0.048	0.830	1.100	0.032	0.0040	8.210	18.18	0.114			

B) Tensile test / Hardness / Charpy

Specimen No.	Rp 1.0 Proof Stress	Tensile Strength	Elongation	Hardness	ISO Probe Energy Charpy Impact				
Nr. / No	mpa	mpa	%	HB	Joule				
DIN EN 10213-16 1.4308	≥200	440 640	≥30	-	-	-	-	-	-
yJHD	325	517	48	-	-	-	-	-	-
qWOD	356	522	45	-	-	-	-	-	-
qWCD	368	518	46	-	-	-	-	-	-
IXDD	341	525	46	-	-	-	-	-	-
yHLD	311	528	49	-	-	-	-	-	-
yHMD	352	542	48	-	-	-	-	-	-

C) Dimer sional check and NDT

Testing	Result	Testing	Result
Visual inspection & dimensional check	OK	Radiographic examination	N/A
Surface crack inspection	N/A	Intergranular corrosion testing (ASTM A 262)	N/A

D) Remarks : 23°C temp

Delivery Condition :

☒ Pickling

☐ Anti-rust

Place:ZhongShan G.D

Date:Apr.10.2026

Works inspector: x Y13