




event_uid: vehicle_instability_allraw_hzh_2025_09_26_20_50_27_000337435
 sample_id: vehicle_instability_allraw_hzh_2025_09_26_20_50_27_000337435_pre3_label3_response_coverage
 road=straight old_phase=primary level=extreme_active morphology=multi_correction
 best RMSE: dir-gated KNN=1.624; RBF KRR=1.677
 worst RMSE: peak-scaled template=1.890; formal ridge=1.789