


Rank 5 recurrent bad event | random_main | gf 2025_09_26_10_52_57



event_uid: vehicle_instability_allraw_gf_2025_09_26_10_52_57_000066795
 sample_id: vehicle_instability_allraw_gf_2025_09_26_10_52_57_000066795_pre2_label2_old_main
 road=straight old_phase=secondary level=strong_active morphology=multi_correction
 best RMSE: formal ridge=0.740; dir-gated KNN=0.952
 worst RMSE: KNN template=1.071; peak-scaled template=0.982