




event_uid: vehicle_instability_allraw_hzh_2025_09_27_19_44_05_000407670
 sample_id: vehicle_instability_allraw_hzh_2025_09_27_19_44_05_000407670_pre1_label2_event_trigger
 road=straight old_phase=secondary level=extreme_active morphology=multi_correction
 best RMSE: formal ridge=0.857; peak-scaled template=1.035
 worst RMSE: RBF KRR=1.446; KNN template=1.114