




event_uid: vehicle_instability_allraw_zxy_2025_09_28_16_35_30_000471085
 sample_id: vehicle_instability_allraw_zxy_2025_09_28_16_35_30_000471085_pre3_label3_response_coverage
 road=curve old_phase=secondary level=extreme_active morphology=multi_correction
 best RMSE: KNN template=2.182; formal ridge=2.401
 worst RMSE: dir-gated KNN=2.687; peak-scaled template=2.532